

JOB LOG

SWIFT Services, Inc.

DATE 11-29-17 PAGE NO. 1

CUSTOMER BARRACUDA OPER. Co. WELL NO. #1 LEASE KEILMAN JOB TYPE TOOLS TICKET NO. 30650

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATION AND MATERIALS
				T	C	TUBING	CASING	
	1130							ON LOCATION
								2 7/8 x 5 1/2 TOCE 3090 PERFS e (TOP) 4336' PORT COLLAR e 1637' RBP e 3500' (14 STANDS OUT)
	1145							START TSO-RBP IN WELL
	1315							SET RBP e 3500 - CIRCULATE WELL CLEAN TEST RBP - 1000 PSI - HOLD
	1400							PULL TUBING TO PORT COLLAR - LOCATE - OPEN CEMENT PORT COLLAR TO SURFACE CLOSE PORT COLLAR - TEST - HOLD 1000 PSI RUN OUTS - REVERSE CLEAN RUN TUBING - REVERSE SAND OFF RBP LEAVE RBP SET e 3500' PULL LOT TUBING SWAB DOWN 11-30-17 TO 2000' RIG CREW - RELEASE & PULL RBP
	1730							JOB COMPLETE

THANK YOU WAYNE

JOB LOG

SWIFT Services, Inc.

DATE 11-29-17 PAGE NO. 1

CUSTOMER		WELL NO.		LEASE		JOB TYPE		TICKET NO.	
Barracuda Operating		#1		Keilman		Perf Collar		#31064	
CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATION AND MATERIALS	
				T	C	TUBING	CASING		
	1300								on location 2 7/8" x 5 1/2"
									RBP-3500' P.C. - 1637'
	1330	4	82	✓		300			Roll Hole
	1350	∅	∅	✓		1000			Test Tools * Hold *
	1400	2	12	✓		300			Spot 200# sand (4skt)
	1415								Pull up to P.C.
	1445								Open P.C.
	1450	3 1/2	5	✓		400			Injection Rate
	1500	4	70	✓		400			Pump 70 bbl Mud
		4	14	✓		400			circulate to surface
	1515	4	77 1/2	✓		200			mix 140 skt SMD w/ 1/4" Flu @ 11.2 ppg
									circulate cement to surface *20skt*
	1545	4	9	✓		400			Displace Cement
	1550	∅	∅	✓		1000			Close P.C. * Hold *
	1555	3 1/2	25	✓		300			Run 6 Jts * 140skt total *
									Reverse Clean * 20skt to pit *
	1610								wash up trucks
									TIH to get sand
	1640	3	35	✓		300			Reverse out Sand
	1700								Job Complete

Thank You
Dave Preston Isaac