## Leis Oil Services, LLC

**Invoice** 

1410 150th Rd Yates Center, KS 66783

Date Invoice #	
7/8/2018	1230

Bill To

Petroluem Resources Management Co. 733 Highgrove Park Houston, TX 77057

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description	Rate	Amount
2.75	6-1-18 Pulling unit#1, was pumping, but just slobbering around, pulled to pump, didn't find any issues with pipe, as I stood it before pulling. Replaced pump, ran in.	65.00	178.75
5.5	6-5-18 Pulling unit #41, thread leak 10th joint, 1 new joint. #26, parted 41st, fished out, with tapered tap, new pump, 2 joints.	65.00	357.50
1.75	6-8-18 Pulling unit #32 hole in 22nd joint, 1 new joint.	65.00	113.75
	6-11-18 Pulling unit #S2, hole 36th joint, 2 other bad threads, 3 joints, no pumps available, had trouble with swivel leaking, had to change it out.	65.00	146.25
2 25	6-18-18 Pulling unit #19, pipe split 3rd joint, 1 joint. #20 hole 22nd joint, 1 joint.	65.00	146.25
	6-14-18 Drill pit for #23-18	150.00	150.00
	6-21-18 Drilling for #23-18	5.25	5,785.50
	6-18-18 Cement for surface on #23-18	15.95	207.35
	6-22-18 Pump for cementing #23-18	400.00	400.00
	6-22-18 Pulling unit #43, hole in 39th joint, bad threads on another, pump change. #30, pulled out to 17th joint.	65.00	243.75
3.5	6-25-18 Pulling unit#30, thread leak at 21st joint, hole in 37th thread, 2 joints and pump swap. #24 broken threads under 17th collar, 1 joint.	65.00	227.50
1	6-22-18 Drill pit for #22-18	150.00	150.00
	6-26-18 Drilling for #22-18	5.25	5,890.50
	6-27-18 pump charge for cementing #22-18	400.00	400.00
	6-28-18 Drill pit for 39-18	150.00	150.00
	6-28-18 Drilling for 39-18	5.25	5,785.50
	6-29-18 Cement for surface	15.95	223.30
	6-29-18 pump charge for cementing #39-18	400.00	400.00
	6-29-18 #68 hole in 27th joint, 4 other bad threads, 5 joints.	65.00	130.00
	6-29-18 Drill pit for #49-18	150.00	150.00
	7-2-18 Drilling for #49-18	5.25	5,785.50
	7-3-18 pump charge for cementing #49-18	400.00	400.00
2.75	7-2-18 #6 hole in 38th joint, 2 joints, 1 other bad thread, had to test 6 joints to find hole.	65.00	178.75
	7-2-18 nitrogen for testing pipes	10.00	10.00
3	7-3-18 #20, hole in 22nd joint, 1 joint. #21 hole in collar, 26th joint, 1 collar.	65.00	195.00
2.5	7-6-18 #15, hole in threads 25th joint, 1 other bad thread, 2 joints. When running in, had to cut 2 feet off of top joint and re-thread as we lost 2 feet of hole.	65.00	162.50
	<u></u>	Total	\$27,967.65

408 2,089.88 2,090.06
23-18 6,442.85
24.89 6,440.50
39-18 6,458.80
49-18 6,335.50