Cell 785-324-1041		
Date 11-1-18 2	c. Twp. Range	Russell KS On Location Finish
	et a rate of 14 purcent e generation of the context	Location Alan's house - 15, 18E, N/Into
Lease Michaelis	Well No. 4	Owner Owner
Contractor Southwind	#3	To Quality Oilwell Cementing, Inc. You are hereby requested to rent cementing equipment and furnish
Type Job Surface		cementer and helper to assist owner or contractor to do work as listed.
Hole Size DY4"	т.р. 3041	Charge Alan Vonfeldt
Csg. 85/8"	Depth 3041	Street
Tbg. Size	Depth	City
Tool	Depth	The above was done to satisfaction and supervision of owner agent or contracto
Cement Left in Csg. 15	Shoe Joint 5	Cement Amount Ordered 75 6% 48 4% CC 2% 62
Meas Line	Displace 1814	Bis an in the second part of the second part of the second parts
rents is abland a polyma EQU	IPMENT	Common/05
Pumptrk M No. Cementer Helper	Jairid	Poz. Mix 70
n No Driver	ous	Gel. 3
Bulktrk D. U. No. Driver R	sik	Calcium
and a second	ES & REMARKS	nanti - Hulls
Remarks: Compated	id Cicculat	
Rat Hole		Flowseal in the second and the second second second graduates a second bit is a to
Mouse Hole	ાલક પ્રાપ્ય માં મુખ્યત્વે લક્ષ્ય ઉપયુદ્ધ છે.	Kol-Seal
Centralizers	primetaria unograpo, tuna y di ki	Mud CLR 48
Baskets		CFL-117 or CD110 CAF 38
D/V or Port Collar		Sand
		Handling BO
		Mileage
nerokintesse setestoko ola		FLOAT EQUIPMENT
		Guide Shoe
entre ten tanto da la secon		Centralizer
the second second second second		Baskets
The first of the second second		AFU Inserts
		Float Shoe Latch Down
service of the servic		
		Burnet C. Fra
	n an	Pumptrk Charge Surtace
		Mileage /5
LALA Musican Social Strategy	n ngé si ng tri lina tra lina si Guille ang sang tri	<u>in the second with a provident state</u> and the provident of the <u>second</u> and the <u>second</u> of the second state of the second st
X Signature	11	es manufactures addition of the second se The second sec
	Incall	Total Charge