KOLAR Document ID: 1428823

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

OPERATOR: License #:			ı	API No.	. 15 -				
OPERATOR: License #:				Spot Description:					
Address 1:									
Address 2:									
City:									
Contact Person:					Footages Calculated from Nearest Outside Section Corner:				
Phone: ()					NE NW	SE SW			
Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic Water Supply Well Other: SWD Permit #: ENHR Permit #: Gas Storage Permit #:					County: Well #:				
Is ACO-1 filed? Yes		log attached? Yes	_ I	Date Well Completed:					
Producing Formation(s): List A						(KCC District Agent's Name)			
Depth to		m: T.D							
Depth to	•	m: T.D		Plugging Commenced:					
Depth to		m:T.D		Pluggin	g Completed:				
Show depth and thickness of a	all water, oil and gas forma	ations.							
Oil, Gas or Water	Records		Casing Re	ecord (Si	urface, Conductor & Produc	tion)			
Formation	Content	Casing	Size		Setting Depth	Pulled Out			
Describe in detail the manner cement or other plugs were us		_		-		Is used in introducing it into the hole. If			
Plugging Contractor License #	::		Name:						
Address 1:			Address 2	2:					
City:				State: _		Zip:+			
Phone: ()									
Name of Party Responsible fo	r Plugging Fees:								
State of	County, _			. , SS.					
					Employee of Operator or	Operator on above-described well,			
	(Print Name)				p.o, oo opoidioi oi	Specials. Sit above accombod Well,			

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

W & W Production Company

1150 Highway 39

Chanute, Kansas 66720-5215

Mobile: 620-431-5970

Phone: Office/Home 620-431-4137

Invoice

DATE	INVOICE NO.
12/3/2018	48620

BILL TO Colt Energy C/O Rex Ashlock PO Box 388 1112 Rhode Island Rd. Iola, Kansas 66749

Larry Gregory Lease(732) APT#/5-099-20674 35-32S-17E Labette County, Kansas

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
Pump Truck	Pump Charge Well#10 (API 15-099-30016) 2	1	1,000.00	T00.000,1
Cement	For plugging 71 sacks(No Charge) Run I" to TD pump 26 sacks Portland Cement to Surface & pull out 1". Run 1" down backside & pump 45 sacks Portland Cement to Surface. Pull out 1" & wash up.	71	0.00	0.00
Pump Truck	Pump Charge Well# 21(API 15-099-30025) 2 1/2 Pipe	1	1,000.00	1,000.00T
Cement	For plugging 28 sacks(No Charge) Run 1" to TD pump 28 sacks Portland Cement to Surface. Pull 1"out & wash up.	28	0.00	0.00
Pump Truck	Pump Charge Well# 24(35) API 15-099-20694)	l	1,000.00	1,000.001
Cement	For plugging 71 sacks(No Charge) Run 1" to TD pump 39 sacks Portland Cement to Surface pull 1"out. Hook up & Squeeze 6 sacks Portland Cement into 2 1/2" & Close in at 500#. Ran 1" down backside & pump 26 sacks Portland Cement to Surface on backside. Pull out 1" & wash up.	71	0.00	0.00
Pump Truck	Pump Charge Well# 14(21)API 15-099-19257 4" Pipe	1	1,000.00	1,000.00T
Coment	For plugging 50 sacks Portland Cement (No Charge)	50	0.00	0.00
	Pump Truck Cement Pump Truck Cement Pump Truck Cement	Pump Truck Pump Charge Well#10 (API 15-099-30016) 2 1/2 Pipe For plugging 71 sacks(No Charge) Run 1" to TD pump 26 sacks Portland Cement to Surface & pull out 1". Run 1" down backside & pump 45 sacks Portland Cement to Surface. Pull out 1" & wash up. Pump Truck Pump Charge Well# 21(API 15-099-30025) 2 1/2 Pipe For plugging 28 sacks(No Charge) Run 1" to TD pump 28 sacks Portland Cement to Surface. Pull 1"out & wash up. Pump Truck Pump Charge Well# 24(35) API 15-099-20694) 2 1/2 Pipe For plugging 71 sacks(No Charge) Run 1" to TD pump 39 sacks Portland Cement to Surface pull 1"out. Hook up & Squeeze 6 sacks Portland Cement into 2 1/2" & Close in at 500#. Ran 1" down backside & pump 26 sacks Portland Cement to Surface on backside. Pull out 1" & wash up. Pump Truck Pump Charge Weil# 14(21)API 15-099-19257 4" Pipe For plugging 50 sacks Portland Cement (No	Pump Truck Pump Charge Well#10 (API 15-099-30016) 2 1/2 Pipe Por plugging 71 sacks(No Charge) Run 1" to TD pump 26 sacks Portland Cement to Surface & pull out 1". Run 1" down backside & pump 45 sacks Portland Cement to Surface. Pull out 1" & wash up. Pump Truck Pump Charge Well# 21(API 15-099-30025) 2 1/2 Pipe Pump Truck Pump Charge Well# 28 sacks Portland Cement to Surface. Pull 1"out & wash up. Pump Truck Pump Charge Well# 24(35) API 15-099-20694) 2 1/2 Pipe Pump Truck Pump Charge Well# 24(35) API 15-099-20694) 2 1/2 Pipe Pump Truck Pump Charge Well# 24(35) API 15-099-20694) 2 1/2 Pipe Pump Truck Pump Charge Well# 24(35) API 15-099-20694) Pump Truck Pump Charge Well# 14(21) API 15-099-19257 4" Pipe Pump Truck Pump Charge Well# 14(21) API 15-099-19257 4" Pipe Pump Truck Pump Charge Well# 14(21) API 15-099-19257 4" Pipe Pump Truck Por plugging 50 sacks Portland Cement (No	Pump Truck Pump Charge Well#10 (API 15-099-30016) 2

Sales Tax (7.75%)

Total

Fax#	Fed. I.D. 48-0843238
620-431-3183	carolwimsett4@yahoo.com
	Page 1