

**Notice:** Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION  
OIL & GAS CONSERVATION DIVISION

Form CP-4  
March 2009

Type or Print on this Form  
Form must be Signed  
All blanks must be Filled

**WELL PLUGGING RECORD**  
K.A.R. 82-3-117

OPERATOR: License #: \_\_\_\_\_  
 Name: \_\_\_\_\_  
 Address 1: \_\_\_\_\_  
 Address 2: \_\_\_\_\_  
 City: \_\_\_\_\_ State: \_\_\_\_\_ Zip: \_\_\_\_\_ + \_\_\_\_\_  
 Contact Person: \_\_\_\_\_  
 Phone: ( \_\_\_\_\_ ) \_\_\_\_\_  
 Type of Well: (Check one)  Oil Well  Gas Well  OG  D&A  Cathodic  
 Water Supply Well  Other: \_\_\_\_\_  SWD Permit #: \_\_\_\_\_  
 ENHR Permit #: \_\_\_\_\_  Gas Storage Permit #: \_\_\_\_\_  
 Is ACO-1 filed?  Yes  No If not, is well log attached?  Yes  No  
 Producing Formation(s): List All (If needed attach another sheet)  
 \_\_\_\_\_ Depth to Top: \_\_\_\_\_ Bottom: \_\_\_\_\_ T.D. \_\_\_\_\_  
 \_\_\_\_\_ Depth to Top: \_\_\_\_\_ Bottom: \_\_\_\_\_ T.D. \_\_\_\_\_  
 \_\_\_\_\_ Depth to Top: \_\_\_\_\_ Bottom: \_\_\_\_\_ T.D. \_\_\_\_\_

API No. 15 - \_\_\_\_\_  
 Spot Description: \_\_\_\_\_  
 \_\_\_\_\_ - \_\_\_\_\_ - \_\_\_\_\_ - \_\_\_\_\_ Sec. \_\_\_\_\_ Twp. \_\_\_\_\_ S. R. \_\_\_\_\_  East  West  
 \_\_\_\_\_ Feet from  North /  South Line of Section  
 \_\_\_\_\_ Feet from  East /  West Line of Section  
 Footages Calculated from Nearest Outside Section Corner:  
 NE  NW  SE  SW  
 County: \_\_\_\_\_  
 Lease Name: \_\_\_\_\_ Well #: \_\_\_\_\_  
 Date Well Completed: \_\_\_\_\_  
 The plugging proposal was approved on: \_\_\_\_\_ (Date)  
 by: \_\_\_\_\_ (KCC District Agent's Name)  
 Plugging Commenced: \_\_\_\_\_  
 Plugging Completed: \_\_\_\_\_

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface, Conductor & Production)			
Formation	Content	Casing	Size	Setting Depth	Pulled Out

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Plugging Contractor License #: \_\_\_\_\_ Name: \_\_\_\_\_  
 Address 1: \_\_\_\_\_ Address 2: \_\_\_\_\_  
 City: \_\_\_\_\_ State: \_\_\_\_\_ Zip: \_\_\_\_\_ + \_\_\_\_\_  
 Phone: ( \_\_\_\_\_ ) \_\_\_\_\_  
 Name of Party Responsible for Plugging Fees: \_\_\_\_\_  
 State of \_\_\_\_\_ County, \_\_\_\_\_, ss.  
 \_\_\_\_\_  Employee of Operator or  Operator on above-described well,  
 (Print Name)

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

Submitted Electronically

W & W Production Company

1150 Highway 39  
 Chanute, Kansas 66720-5215  
 Mobile: 620-431-5970  
 Phone: Office/Home 620-431-4137

# Invoice

DATE	INVOICE NO.
12/3/2018	48620

<b>BILL TO</b>
Colt Energy C/O Rex Ashlock PO Box 388 1112 Rhode Island Rd. Iola, Kansas 66749

Larry Gregory Lease(732) 35-32S-17E Labelle County, Kansas	# W-14
API # 15-099-20070	

SERVICED	ITEM	DESCRIPTION	QTY	RATE	AMOUNT
		Run pipe to TD pump 3 sacks gel & 20 sacks Portland Cement. Pull pipe halfway & pump 7 sacks Portland Cement. Pull pipe to 250' & pump 23 sacks Portland Cement to Surface. Pull out pipe & wash up.			
11/29/2018	Pump Truck	Pump Charge Well# 13 (API 15-099-30019) 4" Pipe	1	1,000.00	1,000.00
	Cement	For plugging 50 sacks Portland Cement (No Charge)	50	0.00	0.00
		Run pipe to TD pump 2 sacks gel & 20 sacks Portland Cement pull out halfway & pump 7 sacks Portland Cement. Pull pipe to 250' & pump 23 sacks Portland Cement to Surface. Pull out pipe & wash up.			
11/30/2018	Pump Truck	Pump Charge Well# 8 (API 15-099-30014) 2 1/2" Pipe	1	1,000.00	1,000.00
	Cement	For plugging 55 sacks Portland Cement (No Charge)	55	0.00	0.00
		Squeeze 26 sacks Portland Cement into 2 1/2" & Close in 750#. Run 1" down backside & pump 29 sacks Portland Cement to Surface. Pull out pipe & wash up.			
11/30/2018	Pump Truck	Pump Charge Well# W-14 (API 15-099-20070) 4" Pipe	1	1,000.00	1,000.00
	Cement	For plugging 50 sacks Portland Cement (No Charge)	50	0.00	0.00
				<b>Sales Tax (7.75%)</b>	
				<b>Total</b>	

Fax #	Fed. I.D. 48-0843238
620-431-3183	carolwimsett4@yahoo.com

W & W Production Company  
 1150 Highway 39  
 Chanute, Kansas 66720-5215  
 Mobile: 620-431-5970  
 Phone: Office/Home 620-431-4137

# Invoice

DATE	INVOICE NO.
12/3/2018	48620

<b>BILL TO</b>
Colt Energy C/O Rex Ashlock PO Box 388 1112 Rhode Island Rd. Jola, Kansas 66749

Larry Gregory Leasc(732) 35-32S-17E Labette County, Kansas	<i>API #</i>
<i>15-099-20070</i>	

*cont*

X

SERVICED	ITEM	DESCRIPTION	QTY	RATE	AMOUNT
		Run pipe to TD pump 2 bags of gel & 20 sacks Portland Cement pull halfway & pump 7 sacks Portland Cement, Pull to 250' & pump 23 sacks Portland Cement to Surface. Pull out pipe & wash up. Hook to 4" with iron & Squeeze pressure to 200#.			
11/30/2018	Pump Truck Cement	Pump Charge Well# 20 (API 15-099-30022) For plugging 66 sacks Portland Cement. (No Charge) Run pipe to TD pump 2 sacks gel & 20 sacks Portland Cement. Pull pipe to halfway pump 7 sacks Portland Cement. Pull pipe to 250' & pump 39 sacks Portland Cement to Surface. Pull out pipe & wash up.	66	1,000.00 0.00	1,000.00 0.00
<b>Sales Tax (7.75%)</b>					\$620.00
<b>Total</b>					\$8,620.00

<b>Fax #</b>	<b>Fed. I.D. 48-0843238</b>
620-431-3183	carulwimsett4@yahoo.com