

Customer <u>Rayden Exp</u>		Lease No.		Date <u>1-24-14</u>		
Lease <u>Kennedy</u>		Well # <u>1-9</u>		Service Receipt		
Casing Depth		County <u>Haskell</u>		State <u>KS</u>		
Job Type		Formation		Legal Description <u>9-29-33</u>		
Pipe Data			Perforating Data		Cement Data	
Casing size <u>4 1/2 10.5#</u>		Tubing Size		Shots/Ft		
Depth <u>5755'</u>		Depth		From To		
Volume <u>91 bbl</u>		Volume		From To		
Max Press		Max Press		From To		
Well Connection		Annulus Vol.		From To		
Plug Depth <u>5713'</u>		Packer Depth		From To		
Lead <u>125 SX @ 12 PP6</u>						
60/40 P.O.Z						
Tail in <u>10.0 SX @ 14.8 PP6</u>						
<u>5.1 W.G. 0, 10% Salt,</u>						
<u>6.1 E-15 14# Detonator</u>						
<u>SA Gilsonite</u>						
<u>AAA Cement</u>						
Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log	
<u>0230</u>					<u>On location Rig up</u>	
<u>0145</u>					<u>Safety Meeting</u>	
<u>0210</u>	<u>2500</u>				<u>Pressure Test</u>	
<u>0212</u>	<u>100</u>		<u>5</u>	<u>3.5</u>	<u>Pump Water</u>	
<u>0214</u>	<u>100</u>		<u>12</u>	<u>4.5</u>	<u>Pump Super flush</u>	
<u>0217</u>	<u>100</u>		<u>5</u>	<u>5</u>	<u>Pump Water</u>	
<u>0227</u>	<u>100</u>		<u>9</u>	<u>3.5</u>	<u>Plug Rat Hole</u>	
<u>0238</u>	<u>100</u>		<u>6</u>	<u>4</u>	<u>Plug Mouse Hole</u>	
<u>0243</u>	<u>100</u>		<u>27.7</u>	<u>4.5</u>	<u>Pump 75 SX @ 12 PP6</u>	
<u>0253</u>	<u>100</u>		<u>26.8</u>	<u>4.5</u>	<u>Pump 100 SX @ 14.8 PP6</u>	
<u>0302</u>					<u>Drop Plug wash up</u>	
<u>0307</u>	<u>100</u>			<u>5.6</u>	<u>Start Displacement</u>	
<u>0319</u>	<u>400</u>		<u>75</u>	<u>2</u>	<u>Slow Rate</u>	
<u>0326</u>	<u>1100</u>		<u>91</u>	<u>2</u>	<u>Bump Plug</u>	
<u>0331</u>	<u>0</u>				<u>Release Pressure - float held</u>	
					<u>Shut Down Rig Down</u>	
Service Units		<u>78940</u>	<u>27808/9919</u>	<u>3811.1 37724</u>		
Driver Names		<u>Ruben</u>	<u>Connel</u>	<u>Ever</u>		

Clint
Customer Representative

Jerry Bennett
Station Manager

Ruben Martinez
Cementer