

620-364-1311 - OFFICE, 620-364-6646 - CELL

WELL CEMENTING

SERVICE TICKET

CHARGE TO

ADDRESS

LEASE & WELL NO.

KIND OF JOB

DIR. TO LOC.

Birk Petroleum

COUNTY

DATE:

CITY

CITY

ST

ZIP

CONTRACTOR

SEC

TW

RG

OLD

NEW

QUANTITY	MATERIAL USED	SERV. CHG
32 SX.	Portland Cement	
	BULK CHARGE	
	BULK TRK. MILES	
	PUMP TRK. MILES	
	PLUGS	
	TOTAL	

T.D. 1024

CSG. SET AT

VOLUME

SIZE HOLE _____

TBG SET AT

VOLUME

MAX. PRESS. _____

SIZE PIPE 2 1/8"

PLUG DEPTH _____

PKER DEPTH	PLUG USED
1	1
2	1
3	1
4	1
5	1
6	1
7	1
8	1
9	1
10	1
11	1
12	1
13	1
14	1
15	1
16	1
17	1
18	1
19	1
20	1
21	1
22	1
23	1
24	1
25	1
26	1
27	1
28	1
29	1
30	1
31	1
32	1
33	1
34	1
35	1
36	1
37	1
38	1
39	1
40	1
41	1
42	1
43	1
44	1
45	1
46	1
47	1
48	1
49	1
50	1
51	1
52	1
53	1
54	1
55	1
56	1
57	1
58	1
59	1
60	1
61	1
62	1
63	1
64	1
65	1
66	1
67	1
68	1
69	1
70	1
71	1
72	1
73	1
74	1
75	1
76	1
77	1
78	1
79	1
80	1
81	1
82	1
83	1
84	1
85	1
86	1
87	1
88	1
89	1
90	1
91	1
92	1
93	1
94	1
95	1
96	1
97	1
98	1
99	1
100	1

TIME FINISHED: _____

REMARKS:

Ran 1" pipe into T.D. Connect to pipe. Pump cement into well. to surface. Pulled 1" out to depth of 500'. Pump and circulate to surface again. Pulled 1" pipe out. Topped well off with cement. cement to surface.

NAME _____

CEMENTER OR TREATER

OWNER'S REP