KOLAR Document ID: 1632610

Kansas Corporation Commission Oil & Gas Conservation Division

Form U-7 August 2019

CASING MECHANICAL INTEGRITY TEST

Maximum Authorized Injection Pressure: psi Maximum Injection Rate: bbl/d Conductor Surface Intermediate Production Liner Tubin Size: Size: Size: Size: Set at: Set at: Set at: Set at: Type: Set at: Set at: Set at: Type: Set at:
Address 2:
Contact Person:
Contact Person:
Well Construction Details: New well Existing well with changes to construction Existing well with no changes to construction Maximum Authorized Injection Pressure: psi Maximum Injection Rate: bbl/d Conductor Surface Intermediate Production Liner Tubin Size: Size: Set at: Set
Maximum Authorized Injection Pressure: psi Maximum Injection Rate: bbl/d Conductor Surface Intermediate Production Liner Tubin Size: Size: Size: Size: Set at:
Maximum Authorized Injection Pressure: psi Maximum Injection Rate: bbl/d Conductor Surface Intermediate Production Liner Tubin Size: Size: Size: Size: Set at: Set at: Set at: Set at: Type: Set at: Set at: Set at: Type: Set at:
Maximum Authorized Injection Pressure: psi Maximum Injection Rate: bbl/d Conductor Surface Intermediate Production Liner Tubin Size: Size: Size: Size: Set at: Set at: Set at:
Conductor Surface Intermediate Production Liner Tubin
Size: Size: Size: Set at:
Set at: Set at: Set at: Set at: Set at: Set at: Sex
Sacks of Cement:
Cement Top: Cement Bottom: Packer Type:
Cement Bottom:
Packer Type:
DV Tool Port Collar Depth of: feet with sacks of cement TD (and plug back): feet with feet with feet with sacks of cement TD (and plug back): feet with _
Zone of Injection Formation: Top Feet: Bottom Feet: Perf. or Open Hole: Is there a Chemical Sealant or a Mechanical Casing patch in the annular space? Yes No If Dual Completion - Injection is: Above Production Below Production FIELD DATA GPS Location: Datum: NAD27 NAD83 WGS84 Lat: Long: Date Acquired: MIT Type: MIT Reason: MIT Reason:
Is there a Chemical Sealant or a Mechanical Casing patch in the annular space? Yes No If Dual Completion - Injection is: Above Production Below Production FIELD DATA GPS Location: Datum: NAD27 NAD83 WGS84 Lat: Long: Date Acquired: MIT Type: MIT Reason: Pressures: Set up 1
FIELD DATA GPS Location: Datum: NAD27 NAD83 WGS84 Lat: Long: Date Acquired: MIT Type: MIT Reason: Time in Minute(s): Pressures: Set up 1
FIELD DATA GPS Location: Datum: NAD27 NAD83 WGS84 Lat: Long: Date Acquired: MIT Type: MIT Reason: Pressures: Set up 1 Pres
Time in Minute(s):
Pressures: Set up 1
Set up 2
Set up 3
Tested: Casing or Casing - Tubing Annulus System Pressure during test: Bbls. to load annulus:
Test Date: Using: Company's Eq
The zone tested for this well is between feet and feet.
The test results were verified by operator's representative:
Name: Phone: ()
·
KCC Office Use Only State Agent: Title: Witness: Yes [
The results were: Remarks:
The results were: Remarks:
Satisfactory
Satisfactory Not Satisfactory

Form	U7 - Casing Mechanical Integrity Test
Operator	American Warrior, Inc.
Well Name	BURGESS 2
Doc ID	1632610

Injection Zones

FormationName	Тор	Bottom
CHEROKEE	5003	5018
CHESTER	5235	5241
ST LOUIS	5487	5494

Conservation Division District Office No. 1 210 E. Frontview, Suite A Dodge City, KS 67801



Phone: 620-682-7933 http://kcc.ks.gov/

Laura Kelly, Governor

Dwight D. Keen, Chair Susan K. Duffy, Commissioner Andrew J. French, Commissioner

FAILED MECHANICAL INTEGRITY TEST (MIT) DEADLINE FOR COMPLIANCE

03/10/2022

LICENSE 4058 American Warrior, Inc. PO BOX 399 GARDEN CITY, KS 67846-0399

Re: API No. 15-081-20363-00-01 Permit No. E26414.1 BURGESS 2 3-29S-32W Haskell County, KS

Operator:

On 03/09/2022, the referenced well failed a mechanical integrity test. Under K.A.R. 82-3-407(c), you have 90 days to:

- 1) repair and retest the well to show mechanical integrity,
- 2) plug the well, or
- 3) isolate all leaks to demonstrate the well does not pose a threat to fresh or usable water or endanger correlative rights.

The well must be shut-in and disconnected until it complies with K.A.R. 82-3-407(c).

Failure to comply with K.A.R. 82-3-407(c) by 06/07/2022 shall be punishable by a \$1,000 penalty.

Please contact this office as soon as possible to let us know your plans for this well.

Sincerely,

Eric MacLaren KCC District #1