KOLAR Document ID: 1642255

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4 March 2009 Type or Print on this Form Form must be Signed All blanks must be Filled

OPERATOR: License #:	API No. 15
Name:	Spot Description:
Address 1:	Sec Twp S. R East West
Address 2:	Feet from North / South Line of Section
City: State: Zip: +	Feet from East / West Line of Section
Contact Person:	Footages Calculated from Nearest Outside Section Corner:
Phone: ()	NE NW SE SW
Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic Water Supply Well Other: SWD Permit #: SWD Permit #:	County: Well #: Lease Name: Well #:
Is ACO-1 filed?	The plugging proposal was approved on: (Date)
Producing Formation(s): List All (If needed attach another sheet)	by: (KCC District Agent's Name)
Depth to Top: Bottom: T.D	Plugging Commenced:
Depth to Top: Bottom: T.D	Plugging Completed:
Depth to Top: Bottom: T.D	

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water	Records	Casing Record (Surface, Conductor & Production)				
Formation	Content	Casing	Pulled Out			

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Plugging Contractor License #:	Name:
Address 1:	Address 2:
City:	State: Zip: +
Phone: ()	
Name of Party Responsible for Plugging Fees:	
State of County,	, ss.
(Print Name)	Employee of Operator or Operator on above-described well,

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

Submitted Electronically

	Form 185-2		es.com	QUAS	Fax I G	G 940-6	328 ainesville Office: 9 12-3336 CID	8 FN e, Te 40-6	1 51 xas 7624 12-3336 qesi@qes CEMEN	i0 serve.c	om	NITROG			
BID #:	5271			AFE#/PO#	: 0	12	5161		882	-47					
TYPE / PUI	RPOSE OF J	0B:	PLUG/PTA					SER	VICE POIN	T:	Liberal,	KS			
CUSTOME	R: SCO	UT ENE	RGY PARTNERS					WE	LL NAME:		COLLIN	GWOOD	M2		
ADDRESS:	144(0 MIDV	NAY ROAD					LOC	ATION:		BIG BO	W. KS			
CITY:	DAL	AS		STATE:	тх	ZIP:	75244	со	UNTY:	STA	ANTON		STATE: KS		
DATE OF S	ALE:	4/26/	/2022												
QTY.	CODE		UNIT			OUIPM	ENTUS	ED					JNIT PRICE		MOUNT
75	1000	L	Mile	Mileage - Pie	ckup	- Per Mi	ile		un				\$5.3		MOUNT 398.25
150	1010	L	Mile	Mileage - Eo	uipm	ent Mile	age - Pei	r Mile)				\$8.30) \$	1,245.00
1	5622	L	Per Well	Pumping Se	rvice	Charge	-1						\$2,315.2	5 \$	2,315.25
QTY. 185 150	CODE 5660 5862	YD L L	UNIT Per Sack Per Lbs	MATERIALS Cement - Lite Cotton Seed	e-A		Sul	btota	l for Pun	nping 8	k Equi		Charges JNIT PRICE \$16.54 \$1.05	\$	3,958.50 MOUNT 3,059.90 157.50
	NHOURS:		#1400	RKERS: 3							5 B8		24-2		2.047.40
IVIA			# WO WORKERS	RKERS: 3					5	uptotal	TOT M		Charges	\$	3,217.40 7,175.90
KIRBY H	IARPER						DISCO	UNT	: 5%			ISCOUI	VT \$		358.80
CARLOS				- ·						DISCO	UNTE	D TOT	AL \$		6,817.11
	& NOTE	net 30 d		date of invoice. A f		harge of 1	-1/2% per	the i invo Sigi		te. After flect full	60 days price.	the disc	nt must paid ount will be TURE & D Date:	emoved	



QUASAR ENERGY SERVICES, INC. 3288 FM 51

Form 185-2J

Gainesville, Texas 76240 Office: 940-612-3336 Fax: 940-612-3336 | qesi@qeserve.com

4/26/22 CEMENTING JOB LOG

CEMENTING JOB LOG

ASING DATA We 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Density (PPG) Excess Density (PPG) Excess Density (PPG) Excess Density (PPG) Sk: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	13.5
We 0	rade: 4.7 TD (ft): 0 acker Depth(ft): 0 acker Depth(ft): 0 Density (PPG) Excess Density (PPG) Kx: Density (PPG) Kx: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	
0 0 0 0 0 0 Pa MENT DATA (((((((((((((rade: 4.7 TD (ft): 0 acker Depth(ft): 0 acker Depth(ft): 0 Density (PPG) Excess Density (PPG) Kx: Density (PPG) Kx: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	
0 Gr 0 Gr 0 Pa MENT DATA	acker Depth(ft): 0 acker Depth(ft): 0 Density (PPG) Excess Density (PPG) /sk: Density (PPG) /sk: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	
0 Gr 0 Pa MENT DATA	acker Depth(ft): 0 acker Depth(ft): 0 Density (PPG) Excess Density (PPG) /sk: Density (PPG) /sk: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	
0 Pa MENT DATA (((((((((((((acker Depth(ft): 0 acker Depth(ft): 0 Density (PPG) Excess Density (PPG) /sk: Density (PPG) /sk: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	
0 Pa MENT DATA (gals/ 110 227	acker Depth(ft): 0 acker Depth(ft): 0 Density (PPG) Excess Density (PPG) Kx: Density (PPG) /sk: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	13.5
MENT DATA	Density (PPG) Excess Density (PPG) Excess Density (PPG) Excess Density (PPG) Sk: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	13.5
k k k gals/ 110 227	Density (PPG) Excess Density (PPG) Excess Density (PPG) Excess Density (PPG) Sk: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	13.5
(gals/ 110 227	Excess Density (PPG) Excess Density (PPG) Sk: Density (PPG) - 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	13.5
(gals/ 110 227	Excess Density (PPG) Excess Density (PPG) Sk: Density (PPG) - 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	13.5
gals/ 110 227	Excess Density (PPG) Excess Density (PPG) Sk: Density (PPG) - 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	13.5
gals/ 110 227	Density (PPG) : Excess Excess Density (PPG)	13.5
gals/ 110 227	/sk: Total (bbls): - 660-23 Weight (PPG): Weight (PPG):	
gals/ 110 227	/sk: Total (bbls): 0 - DP07 - 660-23 Weight (PPG): Weight (PPG):	
gals/ 110 227	/sk: Total (bbls): 0 - DP07 660-23 Weight (PPG): Weight (PPG):	
110	0 - DP07 660-23 Weight (PPG): Weight (PPG):	
110	0 - DP07 660-23 Weight (PPG): Weight (PPG):	
227	- 660-23 Weight (PPG): Weight (PPG):	
	Weight (PPG):	
	Weight (PPG):	
the second se	CEMENTER: KIRBY HARPER	
D PUMPED D	ата	
TAL RAT	DEVVDAC	
3		
3		
3		
	SET CIBP RIH W/TBNG TO 650 FT	
3	START PUMPING WATER AHEAD	
3	START MIXING 95 SK LEAD @ 13.5 PF	PG
3	SHUT DOWN CIRC CEMENT TO SUF	RFACE
	POOH W/TBNG	
1	TOP OFF CASING 20 SK	
1	PRESSURE UP ANNULUS 20 SK	
	3 3 3 3 1	3 START MIXING 50 SK LEAD W/HULLS 3 START DISPLACING WITH FRESH WA 3 START DISPLACING WITH FRESH WA SHUT DOWN POOH W/TUBING SET CIBP RIH W/TBNG TO 650 FT 3 START PUMPING WATER AHEAD 3 START MIXING 95 SK LEAD @ 13.5 PI 3 SHUT DOWN CIRC CEMENT TO SUI POOH W/TBNG 1