KOLAR Document ID: 1669546

**Notice:** Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

## Kansas Corporation Commission Oil & Gas Conservation Division

## WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

OPERATOR: License #:	I API No.	15 -				
Name:						
Address 1:	'	•	Twp S. R East West			
Address 2:		Feet from				
City: State: Zip:	+	Feet from	East / West Line of Section			
Contact Person:	Footage	s Calculated from Nea	rest Outside Section Corner:			
Phone: ( )		□ NE □ NW	SE SW			
Type of Well: (Check one) Oil Well Gas Well OG D&A  Water Supply Well Other: SWD Permit #:  ENHR Permit #: Gas Storage Permit #:  s ACO-1 filed? Yes No If not, is well log attached? Yeoducing Formation(s): List All (If needed attach another sheet)  Depth to Top: Bottom: T.D.	Yes No County:  Lease N  Date We The plug by:	lame: ell Completed: gging proposal was app	Well #: (Date) (KCC <b>District</b> Agent's Name)			
Depth to Top: Bottom: T.D.						
Depth to Top: Bottom:T.D.		g Completed				
Show depth and thickness of all water, oil and gas formations.						
Oil, Gas or Water Records	Casing Record (Su	Record (Surface, Conductor & Production)				
Formation Content Casing	Size	Setting Depth	Pulled Out			
Describe in detail the manner in which the well is plugged, indicating where to cement or other plugs were used, state the character of same depth placed from the cha	·		ods used in introducing it into the hole. If			
Plugging Contractor License #:	Name:					
Address 1:	Address 2:					
City:	State:					
Phone: ( )						
Name of Party Responsible for Plugging Fees:						
State of County,						

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.



## CASILLAS PETROLEUM CORP WELL SERVICE REPORT

ay, August 25, 2022 r 1 , K & L, Excel wireline, Borderline well. roustabout, HP Serv.	KB to GL: Csg Size: Csg Size: Tbg Size: Packer: PBTD:	8 1/2 5 1/2 2 3/8 2,690	Set @ Set @ Set @	538 2,707 2,673	-	099
, K & L, Excel wireline, Borderline well. roustabout, HP Serv.	Csg Size: Csg Size: Tbg Size: Packer:	5 1/2 2 3/8	Set @	2,707	= - -	
roustabout, HP Serv.	Csg Size: Tbg Size: Packer:	5 1/2 2 3/8	Set @	2,707	- - -	
	Tbg Size: Packer:	2 3/8			:	
ell. Plug And abandon	Packer:		Set @	2,673	-	
ell. Plug And abandon		2,690				
ell. Plug And abandon	PBTD:	2,690				
	P	erforations:		1	Produ	ction:
	Formation	Тор	Bottom		BOPD	MCFD
		2,658	2,686	i		
				4		
_						

D.T.A.A.D.						
REMARI 8/25/2022	<u>s</u>					
REMARN  8/25/2022  Mowed rig to loc  MRII  Pour new rope socket  Run in with swab first run brought up 125 ft  Made 2 more runs dry  Call for 30 bbls water with surfactant  Pour surfactant down the  Hook up bobb tail to the float did with 8 bbls Pressure up to 500 psi wouldn't;  Run in with swab first run brought up 125 ft  Made 2 more runs dry  Call for 30 bbls water with surfactant  Pour surfactant down the  Hook up bob tail to the float dup with 8 bbls Pressure up to 500 psi wouldn't;  Run down the swab unflange well R/U the elevatores  Hook up bobbtail to sg Runn godown while working the couldn't pump down of  Worked the for 1 hr didn't move  SDFD						
Pour new rope socket						
Run in with swab first run brought up 125 ft						
Made 2 more runs dry Call for 30 bbls water wth surfactant						
Pour surfactant down tbg  Hook up hob tail to the load the with 8 bbls Pressure up to 500 psi wouldn't.	20					
R/D water truck R/U tbg swab and swab down tbg	1-					
Lay down tog swab unflange well K/U tog elevatoes Hook up bobtail to csg Pump down while working tog couldn't pump down o	sg					
Worked tbg for 1 hr didn't move Shut in well drove crew home						
SDFD						
Rig Cost-\$2617.00						
8/26/2022						
8/26/2022 Drove crew to loc R/D top tools R/D top tools R/D unit risea loc						
R/D unit clean loc Move rig to yard.						
Move rig to yard.						
Medina Rig Cost-\$812.00						
8/26/2022 Borderline Drove rig to loc						
8/26/2022 Borderline Drove rig to loc MiRU Drove crew home						
SDFD						
Rig Cost-\$1190.00						
8/29/2022						
Drove crew to loc						
Unflange well						
Spot in wireline and rig up						
RIH with free point found 100% free at 2198'						
Lay down free Pt R/U jay cut						
Load tbg with 8 bbls RIH with Jay cut shot at 2198' pulled 18pts lost 2 pts after	er shot					
Work tbg wouldn't work lose						
R.I.H. with split shot shoot at 2150' pulled 20 pts on tbg lost 2 pts						
Drowe crew to bec.  Aft Utsg tools  Unflange well  Spot in wireline and rig up  88H with free point found 100% free at 2198' Lay down free Pt R/U jay cut  Walk on water truck to put water down tig  Load tig, with 8 bibs RH with jay cut shot at 2198' pulled 18pts lost 2 pts after  Work tig wouldn't work lose  RJ.H. with split shot shoot at 2150' pulled 20 pts on tig lost 2 pts  Work tig for 1.5 hrs got out with 1 jt tig quit moving						
SDFD						
Rig Cost-\$2840.00						
8/30/2022						
Drove crew to loc						
Unpack well tbg had light blow						
R/U wireline R L H with law cut						
Cut at 1900'						
Work tbg tbg stuck R/U water to tbg load with 2 bbls						
Work tbg still stuck						
Hook up truck to csg , csg was tull press. Up to 350.						
R/U free point R.I.H. with tool found free spot at 1530'						
Trip out of hole , rig up J-cut trip in and cut at 1500'						
Pull up on the turning to right worked the and got out with 4 its then the can	ie free					
Pick up tools drove crew home						
SDFD						
### A STAND AND AND AND AND AND AND AND AND AND						
Rig Cost-\$3620.00						
8/31/2022 Drowe crew to loc. Lay down 46 its from derrick Break down flow lines and sales line from meter run Roustabouts removed unit and dug out cellar and exposed surface pipe Break off stroper bow and loosen well head RJU wireline run in hole with perf guns and tag @ 1101' come up to 575'sho						
Drove crew to loc						
Lay down 46 its from derrick						
Roustabouts removed unit and dug out cellar and exposed surface pipe						
Break off stripper bowl and loosen well head						
R/U wireline run in hole with perf guns and tag @ 1101' come up to 575'sho	ot 4 holes					
Roustabout cut window on surface csg hook up water truck to csg and pump Loaded with 3 bbls press. Up to 300 psi didn't break through	water down c	sg				
R/D truck and wireline						
R/D truck and wireline Shut in well drove crew home SDFD						
SDFD						
Rig Cost-\$2510.00						
9/1/2022 Drove crew to loc						
Drove crew to loc						
Uriver crew to loc.  Rf. Uwater truck to csg  Pumped 50 bbls water down csg @450 psi never circulated up  Rf. D truck RfD unit  Clean loc move rig  Casillas roustabouts cut bigger opening on surface csg and welded on thread						
R/D truck R/D unit						
Clean loc move rig						
Casillas roustabouts cut bigger opening on surface csg and welded on thread	ed 2" fitting					
Rig Cost-\$1450.00						
9/7/2022						
Drove crew to loc						
Drove crew to loc  R/U tbg tools and and cement trucks Trip in hole with 41 jts and tagged with 1/2 of jt on 42nd at 1291'  Pull out with 42nd and set tbg @ 1275'w/ 41 jts						
Pull out with 42nd and set thg @ 1275'w/ 41 jts  Wait on water truck _numn 50 sy cmt w/ 200# huels _Full circulation						
Wait on water truck , pump 50 sx cmt w/ 200# huels. Full circulation Pull tbg to 560' circulate cement up 5 1/2 csg to surface w/ 60 sx .						
Full tig to 500 circulate certient up 3.1/2 Csg to surface w/ 60 sx.  T.O.O.H. w/ rest of the and hook up to 5.1/2 csg pump 120 sx thru perfs @ 5.  Pump 60 sx down 5.1/2 x 8.5/8 annuler @ 200 psi.  Rig down trucks move off of loc	'5' with no circ	ulation to s	urface			
Rig Cost-\$2725.00						
9/14/2022 Roustabouts drove to loc Load up unit cap well off						
Back fill pits and cellar						
Clean loc move equipment to yard						
		-	-	-	-	-
		•	•	-	•	-
ROD FAILURE	TUBING I	FAILURE				
No. of rods         Grade         Type of Break           to fall         Size         of rod         Pin         Body         Outside	No. of jts to fail	Size	Grade of Tbg	Pin	Failure In Collar	Body
Outside						
	1	<u> </u>	Cause of I	failure	<u> </u>	
	Thread Leak	Hole	Split	Bent	Cracked	Parted
Pump: TOTAL MATERIAL IN W	ELL					
Replace Type size	# of Joints	Length		size	# of Rods	Length

					Cause of Failure						
						Thread					
						Leak	Hole	Split	Bent	Cracked	Parted
				•							
-											
Pump:				TOTAL MATE	RIAL IN WE	LL					
	Replace		Type		size	# of Joints	Length		size	# of Rods	Length
	Repair Rerun		Tbg. Pump	Tbg Pulled				Rods Pulled			
	No Repair		Insert Pump								
Replacement											
Pump OUT description:		Tbg Ran				Rods Ran					

PUMPING UNIT		Gas:	Electric:	
Size:	Time Clock Minutes:	On:	Off:	
Stroke:	Tubing Coating	Bare:	Plastic:	
SPM:				
Pump Capacity BPD:	Avg Production:	BOPD:	BWPD:	MCFPD:

		⊢ /			
		- *	MISC	\$21,670	
			WATER		
Casillas roustabouts	\$3,690		SUPERVISION	\$500	
HP Serv.	\$5,512		LABOR		
Excel	\$11,640		RENTAL		
k and I	\$828		STIMULATION		
			RIG	\$ COST \$17.764	