KOLAR Document ID: 1776902

**Notice:** Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

## Kansas Corporation Commission Oil & Gas Conservation Division

## WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

| OPERATOR: License #:  |                                      |         |   | API No. 15  |                         |   |
|---|--------------------------------------|---------|---|---|-------------------------|---|
| Name:   |                                      |         |   | Spot Description:   |                         |   |
| Address 1:  |                                      |         |   | Sec Twp S. R East West  |                         |   |
| Address 2:  |                                      |         |   | Feet from North / South Line of Section Feet from East / West Line of Section |                         |   |
| City:   |                                      |         |   |   |                         |   |
| Contact Person:   |                                      |         |   | Footages Calculated from Nearest Outside Section Corner:                      |                         |   |
| Phone: ( )  |                                      |         |   | NE NW SE SW   |                         |   |
| Type of Well: (Check one) Oil Well Gas Well OG D&A Cathodic  Water Supply Well Other: SWD Permit #: |                                      |         |   | County: Well #:   |                         |   |
| ENHR Permit #:  | ENHR Permit #: Gas Storage Permit #: |         |   |   |                         |   |
| Is ACO-1 filed? Yes No If not, is well log attached? Yes No   |                                      |         |   | The plugging proposal was approved on: (Date)                                 |                         |   |
| Producing Formation(s): List All (If needed attach another sheet)                                   |                                      |         |   | by: (KCC <b>District</b> Agent's Name) Plugging Commenced:                    |                         |   |
| Depth to Top: Bottom: T.D   |                                      |         |   |   |                         |   |
| Depth to Top: Bottom: T.D   |                                      |         |   | Plugging Completed:   |                         |   |
| Depth to Top: Bottom:T.D  |                                      |         |   |   |                         |   |
|   |                                      |         |   |   |                         |   |
| Show depth and thickness of a   | all water, oil and gas forma         | ations. |   |   |                         |   |
| Oil, Gas or Water Records   |                                      |         | Casing Record (Surface, Conductor & Production) |   |                         |   |
| Formation   | Content                              | Casing  | Size  |   | Setting Depth           | Pulled Out                                  |
|   |                                      |         |   |   |                         |   |
|   |                                      |         |   |   |                         |   |
|   |                                      |         |   |   |                         |   |
|   |                                      |         |   |   |                         |   |
|   |                                      |         |   |   |                         |   |
| Describe in detail the manner cement or other plugs were us   |                                      | _       |   |   |                         | Is used in introducing it into the hole. If |
| Plugging Contractor License #:  |                                      |         |   | e:  |                         |   |
| Address 1: Address  |                                      |         |   | :   |                         |   |
| City:   |                                      |         | ;   | State:  |                         | Zip:+                                       |
| Phone: ( )  |                                      |         |   |   |                         |   |
| Name of Party Responsible for   | r Plugging Fees:                     |         |   |   |                         |   |
| State of  | County, _                            |         |   | , ss.   |                         |   |
|   | <i>3</i> , –                         |         |   | _   | implayed of Onerster -  | Operator on obeyed decertibed               |
| (Print Name)  |                                      |         |   | E   | imployee of Operator or | Operator on above-described well,           |

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

## Salley 1-2 15-189-22210-00-01 <u>Well Plugging Record</u>

**5/6/2024:** Held TGSM. Rig up rig. LD polish rods and took off pumping tee. Work rods. Try to unseat pump back off 2-4 ft subs and 6 ft 1- 5/8 rod. Switch equipment over to pull tpb. Try to work tbp but was stuck. Change back over to rods. Put 5/8 rod back on but kept braking in same spot. Shut in well. Will get 3/4 rod out in the morning. Crew drove home.

**5/7/2024:** Held TGSM. Open up well. Pick up 2-3/4" rods and cross over from 5/8" to 3/4". TIH. Made up rods. Started working rods back off. 26 5/8" more rods. TOH with rods to see how much we had. TIH to get deeper break but couldn't get deeper break. Had to parted rods. TOH with rods. Only had 3 ft made up. RIH. Latch on rods. Parted rods came out with small pieces. Shut in well. Crew drove home.

**5/8/2024:** Held TGSM. Open up well. RIH. Get on fish. Back off rods. Got to 1925'. LD rods. 77 – 5/8" rods. Called state and was ok with the footage. RU wireline. RIH with free point. Free point was at 1936'. Changed out tools. Cut tubing @ 1936'. Stund back tubing in derrick. RU wireline. RIH with BP. BP set at 1710'. TIH to 1710'. Spot 30 sacks. LD tubing but on stripping rubber. Casing not tested. RU wireline. Set BP at 810'. Change out tool RIH to 780'. Perforate. Pick up 1 joint. Got injection rate squeeze. 350 sacks to surface. Loss circulation. Shut in well. Crew drove home.

**5/9/2024:** Held TGSM. Open up well. Pick up 25 joints. Tag top of cement at 770'. Pump 50 sacks to surfaces and LD tubing. Top of 5.5" with 30 sacks. Hook up to surface. Pump 105 sacks to get pressure up, but never did. Waited four hours and pump 40 more sacks that state wanted to down to 8-5/8" casing. Shut in well.

**5/10/2024:** Held TGSM. Opened up pump. 70 sacks down 8-5/8" casing. Wash up cement equipment. Rig down. Move rig to next location.