


Sec. 16 Twp. 25 R. 5-E

Well No. #47 Robinson Farm

Deep Rock Company

NORTH



330 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

Elev. 1352

1943

R E P O R T

10/27 Machine

11/3 "

11/10 15" @ 220
Drlg. 550

11/17 Drlg. 1405
12" @ 855'

11/24 KC 2010- 8" @ 2040'
Drlg 2175'

12/1 Miss 2430
SS 0 2430-40
TD 2456
7" @ 2440 WOC.

12/8 TD 2515 PB 2497
20 qts 2445-65 CO

12-15 Viola 2568'
TD 2572&
Run 5"

12/22 5" @ 2572
HFW 2600
PB 2490

12/29 PB 2465 400' oil in 2 hrs

1944

1-5 " " "

1-2 " " "

OVER

1944
/ 1/19

5" @ 2572
Miss 2400
Viola 2568
TD 2572
Perf. Miss
Pump 125 Pot.
Gravity 36

COMPLETED

KANSAS

Map No. 14 Sec. 16 Twp. 25 R. 5EWell No. 47 RobinsonDeep Rock CompanyFIRST REPORT Contractor

NW SW

SECTION PLAT

330 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

0			

Miscellaneous

Location _____

Rig up _____

Drilling and Remarks:

Machine

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

OCT 27 1943

19

S. J. LEWIS

Scout

KANSAS

Map No. 14 Sec. 16 Twp. 25 R. 5E

Well No. 47-^rRobinson

Deep Rock Company

COMPLETED

Contractor

NW SW

SECTION PLAT

330 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

o			

Miscellaneous

Location _____

Rig up _____

Drilling and Remarks:

Wire 2480
Viola 2568
5' @ 2572
Perf. 9' wire
Pump 125 P.T.

36^o / 44

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth 2572

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JAN 19 1944 19

S. J. LEWIS

Scout