


Map No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry Farm _____Benedum & Sons Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up 7/13

Drilling Remarks:

Drilling Remarks:

9/30-2460-H.F. Water10/14-2720-21. Q.10/31-297010/28-3027-21. Q. = 11/14 = 11/18.3050 = 11/253330 = On sand = 12/23350 = 12/93480 = 12/23Plugging 12/28

RECORD

Cased _____ in _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Map No. _____ Sec. 36 Twp. 30 R. 3
 Well No. 1 Curry Farm
Benedum & Sons Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up 7/13

Drilling and remarks

rigging up.

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

7/22, 1916 H. Forsworth Scout

Map No. _____ Sec. 36 Twp. 30 R. 3
 Well No. 1 Curry Farm
Benedict & Treas Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

700

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 h.s. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

8/14, 1916 H. Farnsworth Scout

Map No. _____ Sec. 36 Twp. 30 R. 3
 Well No. 1 Curry Farm _____
Benedict & Sons Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

1000

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

8/19, 1916 L. H. Forns Scout

Map No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry FarmBenedum & Sons Company

NORTH



SOUTH

Location _____

Rig Up _____

Drilling and remarks

1580

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


8/26, 1916E. H. West Scout

*Cowley*Map No. _____ Sec. *36* Twp. *30* R. *3*Well No. *1* *Curry* Farm
Benedum & Drees Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

1750

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

*9/2**1916**E. H. Wood*


Scout

Cowley Sec. *36* Twp. *30* R. *3*
 Map No. _____
 Well No. *1 Curry* Farm _____
Benedum & Jones Company _____

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

✓
2200

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

9/9, 191 *6*


E. Hoover

Scout

Map No. _____ Sec. 36 Twp. 30 R. 3
 Well No. 1 Curry Farm _____
Benedum & Sons Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

U.R. 2220

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

9/16, 1916E. Hunt

Scout

Cowley
 Map No. _____ Sec. *36* Twp. *30* R. *3*
 Well No. *1 Berry* Farm _____
Ohio Oil Company _____

NORTH



SOUTH

Location _____

Rig Up _____

Drilling and remarks

✓ 2350

Hole full water

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

9/23

191 *6*


E. West

Scout

Cowley
 Map No. _____ Sec. *36* Twp. *30* R. *3*
 Well No. *1* *Curry* Farm
Ohio Oil Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

*2460**H. F. water*

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


*9/30*191 *6**E. H. West* Scout

Map No. Cowley Sec. 36 Twp. 30 R. 3
 Well No. 1 Curry Farm
Beaudin & Treas Company

NORTH

WEST

EAST



SOUTH

Location

Rig Up

Drilling and remarks

2640H. J. water

RECORD

Cased..... in. Ft.

Sand

Gas

Oil

Total Depth

PRODUCTION

1st 24 hrs. Nat.

1st 24 hrs. after shot

Gas

Dry Hole

Abandoned

Date

10/71916

Scout

E. H. West


County *Cowley* Sec. *36* Twp. *30* R. *3*

Map No. _____ Well No. *1* *Curry* Farm

Benidum & Trees Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

UR to 2720

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


10/14, 191 *6**Examiner* Scout

COWLEYMap No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry _____ Farm _____

Benedum & Trees Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks _____

✓ 2970 Blk slate
2 ft. dry sand at 2940
hole caving

looks unfavorable
for showing oil.

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

OCT 21 1916


_____, 191____ E. H. WEST Scout

COWLEYMap No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry Farm _____

Benedum & Trees Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

U.R.-3027

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

OCT 28 1916

191


E. H. WEST

Scout

Cowley
 Map No. _____ Sec. *36* Twp. *30* R. *3*
 Well No. *1 Curry* Farm _____
Benedict & Jress Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

U.R. to 3027

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

11/4, 191 *6***E. H. WEST**


Scout

COWLEYMap No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry Farm _____

Benedum & Treese Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

U.R. to 3027

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

NOV 11 1916

191

E. H. WEST


Scout

COWLEYMap No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry _____ Farm _____

Benedum & Trees Company

NORTH

WEST



EAST

SOUTH

RECORD

Location _____

Rig Up _____

Drilling and remarks

U.R. to 3027

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

NOV 18 1916

191

E. H. WEST

Scout

COWLEYMap No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry _____ Farm _____Benedym & Trees Company

NORTH

							0

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

✓
3050**RECORD**

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

NOV 25 1916

191

E. H. WEST Scout


COWLEY

Map No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry _____ Farm _____

Benedum & Treco Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

*Casing 5 3/16**will drill in
Tuesday*

RECORD

Cased _____ in. _____ Ft.

Sand 3330 *1 ft in*

Gas _____

Oil *small show*

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

DEC - 2 1916

E. H. WEST

191


Scout

COWLEY

Map No. _____ Sec. 36 Twp. 30 R. 3
 Well No. 1 Curry Farm _____
B + J Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks _____

3350H.F. Water

RECORD

Cased _____ in. _____ Ft.

Sand 3330-3331

Gas _____

Oil very small show

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

DEC - 9 1916

E. H. WEST

191


Scout

COWLEY

Map No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry Farm _____
B + J Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks _____

✓ 3400 H.F. Water

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

DEC 16. 1916

E. H. WEST

191

Scout

COWLEY

Map No. _____ Sec. 36 Twp. 30 R. 3

Well No. 1 Curry Farm

Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up-----

Drilling and remarks

3480 HF water

RECORD

Cased _____ in. _____ Ft.

Sand.....

Gas -----

Oil

Total Depth -----

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot-----

Gas ----- Cu. Ft.

Dry Hole_____

Abandoned -----

Date _____

Date DEC 23 1916

191

E. H. WEST

Scout


COWLEY

Map No. _____ Sec. 36 Twp. 30 R. 3Well No. 1 Curry Farm __________ Benedum & Trees Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks _____

Plugging

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas Hole full water

Oil _____

Total Depth 3540

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole /Abandoned /

Date

DEC 28 1916E. H. WEST

Scout

MAP No. K12 **KANSAS** SEC. 36 TWP. 30S R. 3E

WELL No. 1 L. S. Curry

Benedict Drilling COMPANY

CONTRACTOR

ABANDONED

SECTION PLAT

_____ Ft. FROM N. LINE

_____ Ft. FROM S. LINE

_____ Ft. FROM E. LINE

_____ Ft. FROM W. LINE

LOCATION _____

RIG UP _____

DRILLING AND REMARKS:

OK

RECORD

CASED _____ IN. _____ FT.

SAND _____

GAS _____

OIL _____

TOTAL DEPTH 3540

PRODUCTION

1ST 24 HRS. NAT. _____

1ST 24 HRS. AFTER SHOT _____

GAS _____ CU. FT.

DRY HOLE ☒

ABANDONED ☒

DATE

1-9 1917 _____ SCOUT