


Map No. _____ Sec. 37 Twp 28 R. 4Well No. 1 Hortensius Farm
Silver Leaf Oil Company

NORTH



SOUTH

Location _____

Rig Up 6/22

Drilling Remarks:

Drilling Remarks:

10/2 - 790'10/9 - 1280'10/17 - 1560'10/23 - 1600'1940 - 21.0 = 11/91960 = 11/272100 = 12/42185 = 12/11 = 5.20.2250 = 12/18 = 12/282280 = 1/8/172340 = 1/15

RECORD

PRODUCTION

Cased _____ in _____ Ft.

1st 24 hrs. Nat. _____

Sand _____

1st 24 hrs. after shot _____

Gas _____

Gas _____ Cu. Ft.

Oil _____

Dry Hole _____


Total Depth _____

Abandoned _____

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hortenbower Farm
Silver Leaf Oil Company

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up ☒
 Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____


Date

6/22, 1916 Ed Cardiff Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hortensburg Farm
Seven Leas Company

NORTH

WEST



EAST

SOUTH

Location ✓
 Rig Up ✓
 Drilling and remarks

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

7/28, 1914 McClary Scout

Map No. _____ Sec. 32 Twp. 28 R. 4Well No. 1 _____ Farm __________
Silver Reef Company

NORTH

WEST

EAST

SOUTH

RECORD

Location _____

Rig Up _____

Drilling and remarks _____

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date _____


191 6Scout Alchib

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hunter Farm
Silver Leaf Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

*Rigged up
waiting on
gas*

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

AUG 30 1916

191


Scout

Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hartman Farm
Silver Leaf Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

780

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


9/12, 1916 Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 14011111111111111111 Farm _____
Lebanon Lumber Company _____

NORTH

WEST

EAST



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

400

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION


1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

9/4, 1916 Lebanon Lumber Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hartenbauer Farm _____
Silver Leaf Company _____

NORTH



SOUTH

Location _____

Rig Up _____

Drilling and remarks

Shut Down
for gas

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

9/18, 1916 S. Leary Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Northern Farm
Sever Leaf Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

Shut Down

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

7/27, 1916 Sever Leaf Scout

Map No. _____ Sec. 32 Twp. 28 R. 4Well No. 1 Hailuomen FarmSilver Leaf Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

790

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

10/2, 1916 Scout Scout

Map No. _____ Sec. 32 Twp. 28 R. 4

Well No. 1 Horsebarn Farm

Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up-----

Drilling and remarks

1280

RECORD

Cased in. Ft.

Sand _____

Gas _____

Oil

Total Depth.....

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot-----

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned-----

Date _____


Date 10/9, 1916 Accord Scout

Map No. _____ Sec. 32 Twp. 28 R 4Well No. 1 Hunterbower FarmSilberberg Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

1560

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

10/17, 1916 McClary Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hortonbome Farm
Silver Reef Company

NORTH



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

RECORD
 Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____


PRODUCTION
 1st 24 hrs. Nat. _____
 First 24 h.s. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date 10/25, 1916 S. C. C. C. Scout

Map No. _____ Sec. 32 Twp. 28 R. 4Well No. 1 Harten Avenue FarmSilver Leaf Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig up _____

Drilling and remarks

1940

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st. 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

10/30, 1916, Geo Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Northbourne Farm _____
Silver Leaf Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

*Under-
reaming
1940'*

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


11/9, 1916 Reedley Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Harlemburg Farm
Lincoln Dev Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

Under
Running

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


11/14, 1916 C. C. Depp Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Haulthorn Farm
Silver Leaf Company

NORTH

WEST

EAST



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

*Straight
 Running
 at 1840*

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____


Date

11/20, 1916 C. C. C. Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
Well No. 1 Hunterbower Farm
Silver Leaf Company

NORTH

WEST



EAST

SOUTH


Location _____ Rig Up _____ Drilling and remarks <u>1960</u>	RECORD	
	Cased _____ in.	Ft.
	Sand _____	
	Gas _____	
	Oil _____	
	Total Depth _____	
	PRODUCTION	
	1st 24 hrs. Nat. _____	
	1st 24 hrs. after shot _____	
	Gas _____	Cu. Ft.
	Dry Hole _____	
	Abandoned _____	

Date 11/27, 1916 Carly Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hortenbome Farm
Silver Leaf Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2100'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

12/4, 191, 6 Conley Scout

Map No. _____ Sec. 32 Twp. 28 R. 4Well No. 17 Hartshorn FarmSilver Leaf Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

12/11, 1916 Cordell Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. Hartmanbower Farm
Silver Leaf Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks _____

2250
 6 5/8" casing
 Ported

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

12/18, 1916 C. C. C. Scout

Map No. _____ Sec. 32 Twp. 28 R. 4Well No. 1 Hunterbore FarmSilver Leaf Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

12/28/6 191 Co. 2 Scout

Map No. _____ Sec. 32 Twp. 28 R 4
 Well No. 1 Hartenbower Farm
Silver Leaf Company

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 First 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

1/1, 1917 Cardiff Scout


*Fishing for
 Porter & Co. Inc.
 2250'*

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hartshorn Farm
Silver Leaf Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

*Drilling
up spec
Cock 2288*

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

4/8, 1917 Coil Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hartert Bower Farm
Silver Leaf Company

NORTH



SOUTH

Location _____

Rig Up _____

Drilling and remarks

2400'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

1/22, 1917. Cord Scout

Map No. _____ Sec. 32 Twp. 38 R. 4Well No. 1 Hartman FarmSilver Leaf Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

Shut Down
2400'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

1/29, 1917 Condy Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hartenbreen Farm _____
Silver Leaf Company _____

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

Shut Down
2400'

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____


Date

2-5-7 Carley Scout
 _____ 191 _____

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hartley Lower Farm
Silver Leaf Company

NORTH

WEST



EAST

SOUTH

RECORD

Location _____

Cased _____ in. _____ Ft.

Rig Up _____

Sand _____

Drilling and remarks

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

2/12/1917 7 only Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hartenbore Farm
Empire Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

Shut Down
2400'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

Aug 19, 191*7* *Co. 1* Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hartenbower Farm
Silver Spring Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2520'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

3/26, 1917 Emery Scout

Map No. _____ Sec. 32 Twp. 28 R. 4Well No. 1 Hartman FarmSilver Leaf Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

Shut Down
2400

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

2/26, 1917 C. Carey Scout

Map No. _____ Sec. 32 Twp. 28 R. 4Well No. 1 Hattenbower FarmSilver Leaf Company

NORTH



SOUTH

REMARKS:

Shut Down 2400

Date

3-5-7, 1917C. A. [Signature] Scout

Map No. _____ Sec. 32 Twp. 28 R. 4Well No. 1 Hartshorn FarmSilver Leaf Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

Fishing U.R.
Blips
2400'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


3/12, 1917 Carly Scout

Map No. _____ Sec. 32 Twp. 28 R. 4
 Well No. 1 Hartenbower Farm
Silver Reef Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

*Shut down
2400*

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

3/19, 1917 Carly Scout

Butler
 K11 **KANSAS** SEC. *32* TWP. *78S* R. *VE*
 MAP NO. _____
 WELL NO. *1 Hortentower*
Silver Leaf Oil Co. COMPANY

CONTRACTOR

SECTION PLAT

ABANDONED

			0

_____ FT. FROM N. LINE
 _____ FT. FROM S. LINE
 _____ FT. FROM E. LINE
 _____ FT. FROM W. LINE

LOCATION _____
 RIG UP _____
 DRILLING AND REMARKS:

RECORD

CASED _____ IN. _____ FT.
 SAND _____
 GAS _____
 OIL _____
 TOTAL DEPTH *2756*

PRODUCTION

1ST 24 HRS. NAT. _____
 1ST 24 HRS. AFTER SHOT _____
 GAS _____ CU. FT.
 DRY HOLE *✓*
 ABANDONED *✓*

DATE

April 19*21* SCOUT

Map No. _____ Sec. 32 Twp. 28 R. 4Well No. 1 Hartenbower Farm _____Silver Leaf Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

Dry & plugged2756'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

4/4, 191 7 Cord Scout