


Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Purcell FarmGerman American CompanyGreat Western NORTH

WEST



EAST

SOUTH

Location _____

Drilling Remarks

Q2 10/2 - 10/9 - 10/17 -
 10/23 - Rigging up
 350 = 11/9 -
 550 = 11/14
 2300 = 12/75 - 11/29
 1900 = 12/4
 1980 = 12/11 = 520
 2280 = 12/18 = 12/28
 2600 = 1/8/17 = 1/15

Rig Up 9/12

Drilling Remarks

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.


Dry Hole _____

Abandoned _____

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Purcell Farm _____German-American Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up ✓ _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

9/12, 1916 Deer Scout

Map No. _____ Sec. 33 Twp. 28 R. 4
 Well No. 1 Purcell Farm _____
German American Company

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up ✓ _____
 Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____


Date

9/20/16, 1916 L. A. S. Co. Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Pursell Farm
German-American Company

NORTH

WEST



EAST

SOUTH

Location ✓Rig Up ✓

Drilling and remarks

RECORD

Cased in. Ft.

Sand

Gas

Oil

Total Depth

PRODUCTION

1st 24 hrs. Nat.

First 24 hrs. after shot

Gas Cu. Ft.

Dry Hole


Abandoned

Date

9/27, 1916 Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Russell Farm _____Gerrison American Company

NORTH



SOUTH

Location _____

Rig Up ☒ _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


10/2, 1916 Scout Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Russell Farm __________ Seismic - American Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

_____, 1916 _____ Scout

Map No. _____ Sec. 33 Twp. 28 R. 4
 Well No. 100 Farm _____
German American Company

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up ✓ _____
 Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date


10/17, 1916 Scout Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Perryville Farm _____Gerrard - American Company _____

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

Rigging up

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 h. s. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

Apr 2, 1916 Recon. Co. Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Pursell FarmGreat Western CompanyBarren - NORTH American

WEST



EAST

SOUTH

Location _____

Rig up _____

Drilling and remarks

250

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st. 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

10/30, 1916, LLC Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 10 Purcell Farm _____Great Western Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

350

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


11/9, 1916 Reed Scout

Map No. _____ Sec. 33 Twp. 28 R. 4
 Well No. 1 Pursell Farm _____
Great Western Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

550

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

11/14 191 6 Candy Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Purcell FarmGreat-western Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

825

RECORD

Cased _____ in. _____

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after sho _____

Gas _____

Dry Hole _____

Abandoned _____


Date

1/30, 1916 Conde

Map No. _____ Sec. 33 Twp. 28 R. 4
 Well No. 1 Purcell Farm _____
Great Western Company

NORTH

WEST



EAST

SOUTH

RECORD

Location _____

Rig Up _____

Drilling and remarks

running
off gas

Cased _____ in. _____ Ft.

Sand 1475-Gas 1000000

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

11/29, 1916 Cord Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Purcell Farm _____Great Western Company _____

NORTH



SOUTH

Location _____

Rig Up _____

Drilling and remarks

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas 1770

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

12/4, 1916, Conley Scout _____

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Pursell Farm _____
Great Western Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

Shut Down
1980'
(No gas)

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

12/11, 191 *6* *Conley* Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Pinnell Farm _____Great Western Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2280

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

12/18, 1916 L. C. C. Co. Scout

Map No. _____ Sec. 33 Twp. 28 R. 4
 Well No. 1 Pursell Farm _____
Great Western Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

10/28/6 191 6 Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Purcell FarmGreat Western Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2405'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

1/1, 1917 Condy Scout

Map No. _____ Sec. 33 Twp. 28 R. 4
 Well No. 18 Farm _____
Great Western Company

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

See

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date


1/8, 1917 Condy Scout

Map No. _____ Sec. 33 Twp. 28 R. 4
 Well No. 10 Purcell Farm _____
Great Western Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

Shut Down
at 2600

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

1/13, 1917

Scout

Map No. _____ Sec. 33 Twp. 28 R. 4Well No. 1 Purcell Farm _____Great Western Company _____

NORTH



SOUTH

Location _____

Rig Up _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date _____

1/22, 1917 Cord Scout _____

L 1002
 Map No. R 11 Sec. 33 Twp. 28 R. 4
 Well No. 1 Purcell Farm
Great Western Company

NORTH

WEST



EAST

SOUTH

RECORD

Location.....

Rig Up.....

Drilling and remarks

Cased..... in. Ft.

Sand.....

Gas.....

Oil.....

Total Depth.....

PRODUCTION

1st 24 hrs. Nat.

1st 24 hrs. after shot.....

Gas..... Cu. Ft.

Dry Hole.....

Abandoned.....

Date

1/22, 1917 Purcell Scout

K11 MAP No. KANSAS SEC. 33 TWP. 785 R. 4E

WELL No. 1 Purcell

Great West COMPANY

CONTRACTOR

SECTION PLAT

			0

ABANDONED

_____ FT. FROM N. LINE

_____ FT. FROM S. LINE

_____ FT. FROM E. LINE

_____ FT. FROM W. LINE

LOCATION _____

RIG UP _____

DRILLING AND REMARKS:

RECORD

CASED _____ IN. _____ FT.

SAND _____

GAS _____

OIL _____

TOTAL DEPTH 2730

PRODUCTION

1ST 24 HRS. NAT. _____

1ST 24 HRS. AFTER SHOT _____

GAS _____ CU. FT.

DRY HOLE ☒

ABANDONED ☒

DATE

7-17 192 17 SCOUT