

Rice

KANSAS

SECTION 14 TOWNSHIP Budfeldt RANGE 10W

WELL NO. #1 Budfelt

COMPANY John Lindsay & Chief Drlg.
Chief Drlg.

NORTH SW NW NE

				0			

WEST

EAST

SOUTH

S-513-A

CO. Rice ELEV. _____

SEC. 14 TWP. 18 RGE. 10W

COMPANY Chief Drlg. NO. 1

		0	
FIRST REPORT			
NOV 27 1917			

FARM Budfelt

LOC. SW NW NE

GEOL. _____

CONTR. Co. Tools

POOL Bushton (Abd.)

SPUD _____

MIRT

CO.

LSE.

NO.

SEC.

TWP.

RGE.

~~2~~
CORRECTION

5-513-A

CO. Rice ELEV. 1760 ~~FE~~

SEC. 14 TWP. 18 RGE. 10W

COMPANY _____ NO. 1

DEC 11 57

ABANDONED

~~John Lindas + Chief Dr. 19.~~

FARM Bredfeldt (WAS FR as Chief Dr. 19 #1 Budfeldt)

LOC. SW NW NE

GEOL. _____
CONTR. Co. Tools _____
POOL Bushton (Abd.)
SPUD 11-25-57

MIRT 11-25-57
~~8"~~ 250'
146 2792 TR 2813
BL 2913 L 2935
~~32~~ XC
3249 Arb 3273

DST 3275-85 60" 10' HOCM
60' OCM IBHP 1140/30" FBHP
220/30" DST 3284-88 60" 20'
HOCM (40-5090 w) 60' OCM + w
6' 450CM + w IBHP 1140/30" FBHP
790/30" RTD 3288 20/09

D&A

CO.

LSE.

NO.

SEC.

TWP.

RGE.