

O.W.W.O.

FORM 51 25M 3-49 PETROL

Barton

KANSAS

Section 4 Township 18 Range 14W


Well No. #5 Monroe

Company Continental

NORTH

WEST

EAST



SOUTH

16

Sec. 4 Twp. R. 14W

5 Monroe Farm

Continental Company

Contractor

Boyd Pool


Ft. from N. Line

990' Ft. from S. Line

990' Ft. from E. Line

Ft. from W. Line

NW SE E



1950 Elev. 1940 REPORT

1/25 Spud 1-19-50
13" @ 378'
9" @ 917'

WOC
3/1 13" @ 378'
9" @ 917'
5" @ 3489'
Lansing 3189'
Arb 3438'
TD 3489'
D&A

ABANDONED

O.W.W.O.

1953
8/12 Spud 8-4-53
Lans 3189' Arb. 3438' OTD 3489'
DD 3616' for SWD

8/19 Whip @ 3458
Drlg. 3585'

8/26 RTD 3794' 7" @ 3489'

9/2 N.R.

9/9 "

9/16 "

10/14 "

10/21 "

10/28 "

11/4 "

11/11 "

OVER

1953
11/18 NR
12/16 "

1954
1/6 "
1/13 NR
1/20 "

1/27 Spud 8-4-53
SWD Well
TD 3794'
Lans 3189', Arb 3438'
OTD 3489'
DD3616'
7" @ 3489'
TD 3794'
Regan 3585', PreCamb. 3640',
CO to 3794'
Comp for SWD Well.

ABANDONED

Kansas

Boyd Pool


Map No. _____ Sec. 4 Twp. 18 R. 14WWell No. 5 Monroe

_____ Continental _____ Company

_____ Contractor

NW SE SE

SECTION PLAT



_____ Ft. from N. Line

990 Ft. from S. Line990 Ft. from E. Line

_____ Ft. from W. Line

Barton County

Location _____

Rig up _____

Drilling and Remarks:

Spud 1-19-50

13" @ 378

9" @ 917

WOC

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JAN 25 1950

19

J. E. TYRA

Scout

Kansas

Map No. _____ Sec. 4 Twp. 18 R. 14WWell No. 5 Monroe

Continental etal. _____ Company

Contractor

NW SE SE

E. 1940
SECTION PLAT

_____ Ft. from N. Line

990 Ft. from S. Line990 Ft. from E. Line

_____ Ft. from W. Line

Barton County

Location _____

Rig up _____

Drilling and Remarks:

13" @ 378
 9" @ 917
 5" @ 3489
 Lansing 3189
 and 3438
 D & A.

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth 3489

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

MAR 1 1950 19

J. E. TYRA

Scout

J. G. McGEHEE

ABANDONED

0

J. G. McGEHEE