


Map No. _____ Sec. 11 Twp. 28 R. 4
 Well No. 6 Shreeves Farm _____
Ohio (Shreve) Company _____



Location _____

Rig Up _____

Drilling Remarks:

Drilling Remarks:

RECORD


PRODUCTION

Cased _____ in _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Map No. _____ Sec. 11 Twp. 28 R. 4Well No. 6 Shreeves Farm
Ohio Company

NORTH



SOUTH

REMARKS:

Rig up

FIRST REPORT

Date

3/12, 1917 Cordiff Scout

Map No. _____ Sec. 11 Twp. 28 R. 4Well No. 6. Shreeves Farm _____Ohio Company _____

NORTH

WEST

EAST

SOUTH

Location ✓ _____

Rig Up _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

3/19, 191 7 Cardiff Scout

Map No. _____ Sec. 11 Twp. 28 R 4
Well No. 6 Shreene Farm _____
Ohio Company _____

NORTH



SOUTH

Location _____
Rig Up ✓
Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
1st 24 hrs. after shot _____
Gas _____ Cu. Ft.
Dry Hole _____
Abandoned _____

Date 3/56, 1917 Cordiff Scout

Map No. _____ Sec. 11 Twp. 28 R. 4
 Well No. 6 Shreves Farm _____
Ohio Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

150'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

4/4, 191 7 Cash Scout

Map No. _____ Sec. 11 Twp. 28 R. 4
 Well No. 6 Shreener Farm _____
Ohio Company _____

NORTH



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

685

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

4/10, 191 7 Cardiff


Scout

Map No. _____ Sec. 11 Twp. 28 R. 4Well No. 6 Shreeves Farm _____Oliver Company _____

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

1000'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

4/17 191 7 C. S. J. Scout

Map No. _____ Sec. 11 Twp. 28 R. 4
 Well No. 6 Shreener Farm _____
Ohio Company _____

NORTH



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date


4/24/17, 191 _____ Scout

Map No. _____ Sec. 11 Twp. 28 R. 4
 Well No. 6 Shreene Farm _____
Ohio Company _____

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

Shut Down
1910

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


5/2, 1910 2 C. S. J. Scout

Map No. _____ Sec. 11 Twp. 28 R. 4
 Well No. 6 Shivers Farm _____
Oliver Company _____

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

2100

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

5/8, 191

7

C. J. R. Scout


Scout

Map No. _____ Sec. 11 Twp. 28 R. 4
 Well No. 6 Shreve Farm _____
Ohio Company _____

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

2590'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

5/25/27 191 7 Candys Scout

Map No. ^{K-11} 1002 Sec. 11 Twp. 28 R. 4
 Well No. 6 Shreves Farm
 Oliver Company

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

*Estimated
 good for
 350 Bbls*

RECORD

Cased _____ in. _____ Ft.
 Sand 2614-2631
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date 5/29, 1917 *Conley* Scout