


Map No. _____ Sec. 17 Twp. 26 R. 4
 Well No. 13 Henry Farm _____
Union Oil Company



Location _____

Rig Up _____

Drilling Remarks:

Drilling Remarks:

20 1/2 hrs Surf

2427-2483)

6/11/18

RECORD

Cased _____ in. _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ cu. ft.


Dry Hole _____

Abandoned _____

Map No. K14 Sec. 12 Twp. 26 R. 4Well No. 13 Denny FarmUnion Oil Company

NORTH

WEST



EAST

SOUTH

Location ✓Rig Up ✓

Drilling and remarks

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

FIRST REPORT


Date

3/11, 1918 J. Landry Scout

Map No. _____ Sec. 12 Twp. 26 R. 4Well No. 138 Denny Farm _____
Union Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

SpuddingSea DrillsE. P. Denny

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

3/27, 1911 J. C. Denny Scout

Map No. _____ Sec. 12 Twp. 26 R. 4Well No. 132 Army
Union Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig up _____

Drilling and Remarks:

600

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


APP 3 1918 191 Scout

Map No. _____ Sec. 12 Twp. 26 R. 4

Well No. 132 Farm _____
Union Company

NORTH

WEST



EAST

SOUTH

RECORD	
Location _____	Cased _____ in. _____ Ft.
Rig Up _____	Sand _____
Drilling and remarks	Gas _____
<u>800</u>	Oil _____
	Total Depth _____
	PRODUCTION
	1st 24 hrs. Nat. _____
	1st 24 hrs. after shot _____
	Gas _____ Cu. Ft.
	Dry Hole _____
	Abandoned _____

Date 4/10, 1918 Scout C. C. C.


Map No. _____ Sec. 12 Twp. 26 R. 4

Well No. 13 Farm _____
Union Company

NORTH

WEST

EAST



SOUTH

RECORD

Location _____

Cased _____ in. _____ Ft.

Rig Up _____

Sand _____

Drilling and remarks

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

4/17, 1911 S. C. Giff Scout

Map No. _____ Sec. 12 Twp. 26 R. 4Well No. 13 Denny Farm _____
Union Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

1200

RECORD

Cased _____ in _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

4/24, 1918 J. Carding Scout


Map No. _____ Sec. 12 Twp. 26 R. 4

Well No. 138 Farm _____

_____ Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

1540

RECORD

Cased _____ in. _____ Ft

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

5/1, 1918 Scout

Map No. _____ Sec. 12 Twp. 26 R. 4
Well No. 13 Denny Farm _____
Union Company _____

NORTH



SOUTH

Location _____
Rig Up _____
Drilling and remarks

1790

RECORD

Cased _____ in. _____ Ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
1st 24 hrs. after shot _____
Gas _____ Cu. Ft.
Dry Hole _____
Abandoned _____


Date 5/8, 1918 S. C. Denny Scout

Map No. _____ Sec. 12 Twp. 26 R. 4

Well No. 13 Denny Farm _____
Union Company

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

1800

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

5/15, 1918 S. Conroy Scout

Map No. _____ Sec. 12 Twp. 26 R. 4Well No. 13 Denny Farm_____
Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2160

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

5/22/191Scout

Map No. _____ Sec. 12 Twp. 26 R. 4Well No. 132 _____ Farm
Union _____ Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2250**RECORD**

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

529, 1918 Cooley _____ Scout

Map No. _____ Sec. 12 Twp. 26 R. 4
 Well No. 13 Denny Farm _____
Union Company _____

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

Top of well
2407

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

6/5, 1918 *Candey* Scout _____

Map No. K14 Sec. 12 Twp. 26 R. 4Well No. 138Company UnionContractor Geo. Drilling

NORTH

WEST

EAST

COMPLETED

SOUTH

Location ILRig up IL

Drilling and Remarks:

Est
at 50
Bhs

RECORD

Cased _____ in., _____ ft.

Sand 2427-2483

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

191

Scout