

Map No. _____ Sec. 14 Twp. 26 R. 4Well No. 7-Shrivers Farm __________Empire Company

NORTH

WEST

EAST

SOUTH

COMPLETED

Location _____

Rig Up _____

Drilling Remarks:

Drilling Remarks:

RECORD

Cased _____ in. _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ cu. ft


Dry Hole _____

Abandoned _____

Map No. _____ Sec. 14 Twp. 36 R. 4
 Well No. 7 Shriver Farm _____
Empire Company _____

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up ☒ _____
 Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

FIRST REPORT


Date

8/17, 1917 Cordell Scout _____

Map No. _____ Sec. 14 Twp. 40 R. 4Well No. 7. Shriver Farm _____Empire Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up ☒ _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


8-24, 1917Lantz

Scout

Map No. _____ Sec. 14 Twp. 26 R. 4
 Well No. 7 Shriver Farm _____
Engine Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date 10/9, 1917 Landry Scout

Map No. _____ Sec. 14 Twp. 26 R. 4Well No. 7 Shriver Farm
Engine Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks
900

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

10/17, 1917, Carly Scout

Map No. _____ Sec. 14 Twp. 26 R. 4
 Well No. 7 Shivers Farm _____
Empire Company _____

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

1220

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date


10/24, 1917 Conley Scout

Map No. _____ Sec. 14 Twp. 26 R. 4Well No. 7 Shriver Farm _____

Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2 D 1220

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

10/31, 1917 Conley Scout _____

Map No. _____ Sec. 14 Twp. 26 R. 4Well No. 7 Skinner Farm _____

Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

22/220

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

11-7 191 7 Corby Scout

Map No. _____ Sec. 14 Twp. 26 R. 4
 Well No. 7 Shiner Farm _____
Engine Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

1650

RECORD

Cased _____ in _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

4/14, 1917 C. Conley Scout _____

Map No. _____ Sec. 14 Twp. 26 R. 4
 Well No. 7 Shriver Farm _____
Engine Company _____
 NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

2010

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____


Date

11/21, 1911 7 Carey Scout

Map No. _____ Sec. 14 Twp. 26 R. 4Well No. 7 Shriver Farm _____
Empire Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2155

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

11/28, 1917 Candey Scout

Map No. _____ Sec. 14 Twp. 26 R. 4Well No. 7 Shriver Farm _____Engine Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

Top sand 235312 ft inNo showing

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

12/5, 1917 Candiff Scout _____

Map No. K14 Sec. 14 Twp. 26 R. 4Well No. 7 Shriver Farm
Empire Company

NORTH

WEST



EAST

SOUTH

RECORD

Location -----

Cased ----- in. ----- Ft.

Rig Up -----

Sand 2323-2393

Drilling and remarks

Gas -----

Oil -----

Total Depth -----

PRODUCTION

1st 24 hrs. Nat. -----

1st 24 hrs. after shot -----

Gas ----- Cu. Ft.

Dry Hole -----

Abandoned -----

Date

10/19, 1917 C. S. Jeff Scout