


Map No. _____ Sec. 5 Twp. 26 R. 5Well No. 36 - Linn Farm _____Sinclair Company _____

NORTH

WEST

EAST



SOUTH

Location ✓ ✓Rig Up 11-27-16

Drilling Remarks:

Drilling Remarks:

R. 21 - 12/4 = 12/11
Spalg: 12/18
660' = 12/28
1150 = 1/1
1625 = 1/8/17
1800 = 1/10

RECORD

Cased _____ in _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Map No. _____ Sec. 5 Twp. 26 R. 5Well No. 36 Lima Farm _____Sinclair Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up ☒ _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

4/27, 1916 Condy Scout

Map No. _____ Sec. 5 Twp. 26 R. 5Well No. 36 Linn Farm _____Sinclair Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date

12/4, 1916, Cody Scout

Map No. _____ Sec. 5 Twp. 26 R. 5
 Well No. 36 Primer Farm _____
Sumalin Company _____

NORTH



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

Rigging up

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____


PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date 12/11, 1916, Cardiff Scout

Map No. _____ Sec. 5 Twp. 26 R. 5
 Well No. 36 _____ Farm _____
Lincoln _____ Company _____

NORTH



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

Spreading

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION


1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

12/18, 1916 C. D. Duff Scout _____

Map No. _____ Sec. 5 Twp. 26 R. 5
 Well No. 36 _____ Farm _____
 _____ Company

NORTH



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

660'

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date 12/28/26 _____ 191 _____ Scout Conley

Map No. _____ Sec. 5 Twp. 36 R. 5
 Well No. 36 _____ Farm _____
Shiloh _____ Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

1150'

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

1/1, 191 7 Carley Scout

Map No. _____ Sec. 5 Twp. 26 R. 5
 Well No. 36 _____ Farm _____
Sinaloa _____ Company _____

NORTH

WEST

EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

1625

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION


1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

1/8, 191 2 Conley _____ Scout _____

Map No. _____ Sec. 5 Twp. 26 R. 5
 Well No. 36 Linn Farm _____
Sinclair Company _____

NORTH



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

1800'

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

1/15, 191 7 Co. 1 Scout _____

Scout

Map No. _____ Sec. 5 Twp. 26 R. 5
 Well No. 36 Linn _____ Farm
Swain _____ Company

NORTH

WEST

EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

2340'

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date


1/29, 1917 Conroy Scout

Map No. _____ Sec. 5 Twp. 26 R. 5
Well No. 36 Linn Farm _____
Swain Company _____

NORTH

WEST

EAST



SOUTH

Location _____
Rig Up _____
Drilling and remarks _____

2400'

RECORD

Cased _____ in. _____ Ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
First 24 hrs. after shot _____
Gas _____ Cu. Ft.
Dry Hole _____
Abandoned _____

Date


2/5, 1917 Early Scout _____

Map No. ^{K14} L1004 Sec. 5 Twp. 26 R. 5
 Well No. 36 Lin Farm
Swain Company

NORTH

WEST

EAST



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

Estimated
at 75 Bbls

RECORD

Cased _____ in. _____ Ft.
 Sand 2440-2479
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

5/12, 191 7 Conley Scout