


Map No. _____ Sec. 6 Twp. 26 R. 5Well No. 26 x Marsh Farm __________Empire_____
Company

NORTH

WEST



EAST

SOUTH

Location _____

Drilling Remarks

10/3-66510/11-105010/18-121010/25-160011/9-198011/14-206011/27-2446 Top of sand = 12/4Rig Up 9/20

Drilling Remarks

RECORD

Cased _____ in. _____ Ft.

Sand 2446-2460

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. 300 bbls

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. 1 Farm _____
Empire Company

NORTH

WEST

EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

9/30, 1916 Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
Well No. 123456 Farm _____
_____ Company _____

NORTH

SOUTH

WEST

EAST

Location _____ Rig Up _____ Drilling and remarks <u>110</u>	RECORD
	Cased _____ in. _____ Ft.
	Sand _____
	Gas _____
	Oil _____
	Total Depth _____
	PRODUCTION
	1st 24 hrs. Nat. _____
	First 24 hrs. after shot _____
	Gas _____ Cu. Ft.
	Dry Hole _____
	Abandoned _____

Date

9/26, 1916 Lee Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. 1 Horse Farm _____
Engine Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

665

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

10/3, 1916 Boone Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. 1 Maas Farm _____
Empire Company _____

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION


1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

10/1 191 Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. 1 Morse Farm
Cumprine Company

NORTH



SOUTH

RECORD

Location _____
 Rig Up _____
 Drilling and remarks

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

1210

PRODUCTION

1st 24 hrs. Nat. _____
 First 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date


10/8, 1916 Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. 1 _____ Farm _____
Enterprise Company

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling and remarks

1600

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

10/25-6 _____ 191 _____ Score _____

Map No. _____ Sec. 6 Twp. 26 R. 5Well No. 1 Marshall FarmEmpire Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig up _____

Drilling and remarks

1800

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st. 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

10/30/06, 1916Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. 1 House Farm _____
Empire Company _____

NORTH

WEST

EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks

RECORD
 Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION
 1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date

11/9, 1916 Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. # 26 Union Farm _____
Company Company _____

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2060

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

First 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

11/14, 1916 Scout Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. 26 Ward Farm
Cumprine Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

11/30/1916 Cumprine Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. 26 Wanda Farm _____
Eupine Company _____

NORTH

WEST



EAST

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

Top sand
2446'

RECORD

Cased _____ in. _____ Ft.
 Sand 2446
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date


11/22, 1916 Cordiff Scout

Map No. _____ Sec. 6 Twp. 26 R. 5
 Well No. 26 Marsh Farm _____
Empire Company _____

NORTH

WEST

EAST



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____


Tap sand
2446
Shut Down

Date 12/4, 1916, Cordell Scout

Map No. _____ Sec. 6 Twp. 26 R. 5Well No. 26 Nebraska FarmEmpire Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

*Estimated
good for
300 Bbls
per day*

RECORD

Cased _____ in. _____ Ft.

Sand 2446-2460

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

12/11, 1916 Condeff Scout