

7/28 - Top Granite Wash 2916 -
drlg 2985 -

7/6 _____

7/13 S/D 2997

7/19 _____

7/26 _____

8/2 _____

8/7 _____

8/16 Drlg. 3017

8/23 _____

8/28 Drlg 3020

9/4 - " 3164

9/12 " 3225 ~~line~~

base line 2590'

9/19 - Drlg - 3250'

9/26 _____

10/3 _____

10/10 _____

10/17 - Drlg 3407'

10/24 " 3440'

10/31 " 3503'

11/7 " 3560'

11/14 " 3560'

11/21 " 3569'

11/28 " 3569'

12/4 - chat 1910-13 - dry

HFW 2168'

Base line 2590'

Top granite wash 2916'

T.D. 3600'

Dry & Abandoned

Map No. 10 Sec. 10 Twp. 12 R. 7 ^E

Well No. 1 ^{Chase}
Pioneer Pet Co Company
Contractor

FIRST REPORTS

330 Ft. from N. Line
330 Ft. from S. Line
330 Ft. from E. Line
Ft. from W. Line

SECTION PLAT

			0

Location _____
Rig up _____
Drilling and Remarks:
R.O.S.

RECORD

Cased _____ in., _____ ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
1st 24 hrs. after shot _____
Gas _____ Cu. Ft.
Dry Hole _____
Abandoned _____

Date FEB 15 1928
CHAS. L. SHERWOOD
192 _____ Scout

Map No. 10 Sec. 10 Twp. 12 R. 7

Well No. 1 ^{Chase}
Pioneer Pet Co COMPANY
CONTRACTOR

COMPLETED

330 FT. FROM N. LINE
330 FT. FROM S. LINE
330 FT. FROM E. LINE
FT. FROM W. LINE

SECTION PLAT

			0

ABANDONED

LOCATION _____

RIG UP _____

DRILLING AND REMARKS:
Chat 1910-13' Dry
HW 2168'
Base line 2590'
Top granite wash
2916'
094 3600

RECORD

CASED _____ IN., _____ FT.
SAND _____
GAS _____
OIL _____
TOTAL DEPTH 3600

PRODUCTION

1ST 24 HRS. NAT. _____
1ST 24 HRS. AFTER SHOT _____
GAS _____ Cu. Ft.
DRY HOLE
ABANDONED

DATE DEC 5 1928
CHAS. L. SHERWOOD
192 _____ Scout