


Section 13 Township 17S Range 1E

Well No. 1 McCoy

Company Irwin Daetwiler



Marion

KANSAS

SEC. 13	TWP. 17S	R. 4E
------------	-------------	----------

WELL NO:
#1 McCoy


FARM

COMPANY
Irwon Daetwiler

CONTRACTOR
Slusser

Lost Springs

_____ Ft. from N. Line
 _____ Ft. from S. Line
 _____ Ft. from E. Line
 _____ Ft. from W. Line



SW SW SW

FIRST REPORT

1955	ELEVATION 1461'	REPORT
------	--------------------	--------

7/13 Loc.

8/10 Comm 7-14-55
 M 2320
 TD 2323
 8 5/8" @ 177/135 5 1/2" @ 2321/50
 DD 2341 SSO & Wtr frac
 Comp 23 bopd 20 bw

COMPLETED

County Marion Elev. 1461
 Sec. 13 Twp. 17 Rge. 4E
 Company Irwin Daetwiler
 Farm Name McCoy No. 1

TOPS	DEPTH	LOG	DATUM
Anh.			
TP.			
H.			
Tr.			
Dg.			
BL.			
L.			
K.C.			
B.K.C.			
Ce.			
C.			
M.	2320		8.59
M.			
K.			
Mz.			
Me.			
V.			
S.			
S.			
A.			
R.			
PE.			
G.			
T.D.	2323		

Loc. in Sec. SW SW SW
 Geol. _____
 Contr. Slusser
 Pool Lost Springs

COMPLETE		
0		

Date Comm. 7-14-55 AUG. 10 1955

8 5/8" @ 177/135 - 5 1/2" @ 2321/50

DD 2341 SSO & Wtr. frac

Comp. 23 bopd 20 bw

Co.
 Lse.
 No.
 Sec.
 T.
 R.