

Greenwood Co., Kans.

Sec. 10 Twp. 23 Rge. 9
 Farm. Shelly Oil No. 2
 Elev. _____ T. D. _____
 Log No. _____

nil 5	do 935
sl 34	sl 995
sl 45	do 1000
do 60	sl 1025
sh 115	do 1035
sl 125	sl 1060
do 130	do 1072
sl 150	sl 1105
do 155	do 1115
sl 220	sl 1140
do 235	do 1150
sl 295	sl 1210
do 315	do 1220
sl 355	sl 1225
red sh 360	do 1230
sl 360	sh 1280
do 375	sl & do 1300
sl 450	sl & do 1325
do 455	sl 1379 H.F.W.
sl 520	ss 1425
do 530	broken ls 1430
sl 555	do 1455
do 565	sl 1465
sl 570	do 1501
do 575	do 1635
sl 605	sl 1744
do 613	do 1747
sl 620	ss 1750 3 BW fhr.
do 624	do 1895
sl 645	sandy sh 1900
do 650	sl 1910
sl 660	do 1915
do 665	do 1925
sl 717	sl 2070
do 721	do 2090
sl 726	sl 2124
do 732	do 2139
sl 745	sl 2342
do 753	gas ss 2345
sl 755	sl 2370
do 775	sl 2380
sl 800	oil 2400 to 2404
do 805	sandy do 2384
sl 835	sl 2400
do 855	more oil 2404 to 2411
sl 860	800' oil in hole at 2141 (mistake?)
do 870	do 2404
sl 880	
do 890	
sl 900	
do 905	
sl 925	

