

One copy of all wireline logs and drillers time log shall be attached with this form. Submit CP-4 form with all plugged wells. Submit CP-111 form with all temporarily abandoned wells.

(purchased from city, R.W.D. #)

SIDE TWO

Operator Name Lorraine Cleaver Lease Name Medcalf Well # 22Sec. 7 Twp. 24 Rge. 22 ☒ East ☐ West County Bourbon

WELL LOG

INSTRUCTIONS: Show important tops and base of formations penetrated. Detail all cores. Report all drill stem tests giving interval tested, time tool open and closed, flowing and shut-in pressures, whether shut-in pressure reached static level, hydrostatic pressures, bottom hole temperature, fluid recovery, and flow rates if gas to surface during test. Attach extra sheet if more space is needed. Attach copy of log.

Drill Stem Tests Taken ☐ Yes ☐ No
 Samples Sent to Geological Survey ☐ Yes ☐ No
 Cores Taken ☐ Yes ☐ No

Formation Description
☐ Log ☐ Sample

Name Top Bottom

Core 670-688

Perf 677-681

CASING RECORD ☐ New ☐ Used							
Report all strings set-conductor, surface, intermediate, production, etc.							
Purpose of String	Size Hole Drilled	Size Casing Set (in O.D.)	Weight Lbs/Ft.	Setting Depth	Type of Cement	#Sacks Used	Type and Percent Additives
Surface Production	10 5/8	6 5/8 2 1/2		20 128	Portland Portland	83	60/40-670
PERFORATION RECORD				Acid, Fracture, Shot, Cement Squeeze Record (Amount and Kind of Material Used)			
Shots Per Foot	Specify Footage of Each Interval Perforated					Depth	
8	678-681			2 1/2" Fluids Shot			
TUBING RECORD				Liner Run ☐ Yes ☐ No			
Date of First Production	Producing Method						
M 20 01				☐ Flowing ☒ Pumping ☐ Gas Lift ☐ Other (explain).....			