



Operator Name: Quest Cherokee, LLC Lease Name: Greenwood, Charles R. Well #: 21-1  
 Sec. 21 Twp. 31 S. R. 18  East  West County: Neosho

**INSTRUCTIONS:** Show important tops and base of formations penetrated. Detail all cores. Report all final copies of drill stems tests giving interval tested, time tool open and closed, flowing and shut-in pressures, whether shut-in pressure reached static level, hydrostatic pressures, bottom hole temperature, fluid recovery, and flow rates if gas to surface test, along with final chart(s). Attach extra sheet if more space is needed. Attach copy of all Electric Wireline Logs surveyed. Attach final geological well site report.

Drill Stem Tests Taken <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <i>(Attach Additional Sheets)</i>  Samples Sent to Geological Survey <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No  Cores Taken <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Electric Log Run <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <i>(Submit Copy)</i>  List All E. Logs Run:  <b>Dual Induction Log</b> <b>Compensated Density/Neutron Log</b>	<input checked="" type="checkbox"/> Log Formation (Top), Depth and Datum <input type="checkbox"/> Sample  <table border="0" style="width:100%"> <tr> <td style="width:60%">Name</td> <td style="width:20%">Top</td> <td style="width:20%">Datum</td> </tr> <tr> <td>Lenapah Lime</td> <td>209</td> <td>+694</td> </tr> <tr> <td>Altamont Lime</td> <td>249</td> <td>+654</td> </tr> <tr> <td>Pawnee Lime</td> <td>393</td> <td>+510</td> </tr> <tr> <td>Oswego Lime</td> <td>478</td> <td>+425</td> </tr> <tr> <td>Verdigris Lime</td> <td>604</td> <td>+299</td> </tr> <tr> <td>Mississippi Lime</td> <td>964</td> <td>-61</td> </tr> </table>	Name	Top	Datum	Lenapah Lime	209	+694	Altamont Lime	249	+654	Pawnee Lime	393	+510	Oswego Lime	478	+425	Verdigris Lime	604	+299	Mississippi Lime	964	-61
Name	Top	Datum																				
Lenapah Lime	209	+694																				
Altamont Lime	249	+654																				
Pawnee Lime	393	+510																				
Oswego Lime	478	+425																				
Verdigris Lime	604	+299																				
Mississippi Lime	964	-61																				

CASING RECORD <input type="checkbox"/> New <input type="checkbox"/> Used							
Report all strings set-conductor, surface, intermediate, production, etc.							
Purpose of String	Size Hole Drilled	Size Casing Set (In O.D.)	Weight Lbs. / Ft.	Setting Depth	Type of Cement	# Sacks Used	Type and Percent Additives
Surface	12-1/4"	8-5/8"	24.75#	20'	"A"	4sx	
Production	6-3/4"	4-1/2"	10.5#	997'	"A"	135sx	

ADDITIONAL CEMENTING / SQUEEZE RECORD			
Purpose:	Depth Top Bottom	Type of Cement	#Sacks Used
<input type="checkbox"/> Perforate <input type="checkbox"/> Protect Casing <input type="checkbox"/> Plug Back TD <input type="checkbox"/> Plug Off Zone			
<b>RECEIVED</b> Type and Percent Additives <b>JUL 06 2004</b> <b>KCC WICHITA</b>			

Shots Per Foot	PERFORATION RECORD - Bridge Plugs Set/Type Specify Footage of Each Interval Perforated	Acid, Fracture, Shot, Cement Squeeze Record (Amount and Kind of Material Used)	Depth
None	Waiting on Pipeline		

TUBING RECORD	Size	Set At	Packer At	Liner Run <input type="checkbox"/> Yes <input type="checkbox"/> No
---------------	------	--------	-----------	--

Date of First, Resumerd Production, SWD or Enhr.	Producing Method <input type="checkbox"/> Flowing <input type="checkbox"/> Pumping <input type="checkbox"/> Gas Lift <input type="checkbox"/> Other (Explain)
--	--

Estimated Production Per 24 Hours	Oil Bbls.	Gas Mcf	Water Bbls.	Gas-Oil Ratio	Gravity
-----------------------------------	-----------	---------	-------------	---------------	---------

Disposition of Gas  Vented  Sold  Used on Lease *(If vented, Submit ACO-18.)*

METHOD OF COMPLETION

Open Hole  Perf.  Dually Comp.  Commingled  
 Other (Specify) \_\_\_\_\_

Production Interval