

3764

906

D.S.T. #1



SUPERIOR TESTERS, INC.

433 SOUTH WESTVIEW, DERBY, KANSAS

Date 10/10/76 Ticket No. 3764 Elevation 2233 KB

Total Depth 3823 Tested From 3816 To 3823 Formation Tested Arbuckle

Blow Weak blow 10 minutes and died

Mud Wt. 10 Viscosity 40 Bottom Hole Temp 114

Size Bottom Choke 1/2" Size Top Choke 1/2"

Size Drill Pipe 4 1/2" IF Size Hole 7 7/8" Length Air Chamber - Ft.

Tool Open 20 Hr Min Initial Shut in Time 20 Min Tool Open 20 Hr Min Final Shut in Time 20 Min

Recovery <u>375^t of mud - no trace of</u> <u>water or oil</u>	Office Corrected Pressure Reading Initial Shut in Pressure <u>823</u> Lbs Initial Flow Pressure <u>244</u> Lbs Final Flow Pressure <u>244</u> Lbs Final Shut in Pressure <u>750</u> Lbs Initial Hydrostatic Pressure <u>2078</u> Lbs Final Hydrostatic Pressure <u>2063</u> Lbs
---	---

Remarks Slight packer failure when first on bottom, picked up some mud

Tore up one packer

Witnessed By Marlon B. Dixon

Tool Operator R. E. Budig

Childs
 Name of Lease
 Well No. 1
 Test No. 1
 Location S/2 NW, NW 6-10S-19W
 County Rooks
 State Kansas
 F & M Oil Company, Inc.
 Company