

7/28--Installing pumping equipment and
tanks Will be a week before
taking pumping test (Tel)

8/5--Potential 937 bbls. oil No water
(Telegram)

8/12/36-Sil. 3321'.
Pay 3351-54'.
T.D. 3354'.
4000 gallons of acid.
Potential 937 bbls of oil.

COMPLETED

KANSAS

Map No. 46 Sec. 1 Twp. 19 R. 11WWell No. 1 RickRose Spring Oil CompanyJ. J. Contractor

SECTION PLAT

_____ Ft. from N. Line

1330 Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

our Lease			
0			

FIRST REPORT

Location _____

Rig up _____

Drilling and Remarks:

Cellar

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

PR 29 1936

192

Scout

J. J. LEWIS

Sumner map
R.H.

Returned	
Cards	<i>Sh</i>
Tracing	<i>Gus</i>
France map	
Scarborough map	<i>[Signature]</i>
Moody map	
Scarborough Plat Book	
Moody Plat Book	

Map No. 46 Sec. 1 Twp. 19 R. 11W

Well No. 1 Rick

Rose Spring Twp. Company
J Contractor

SECTION PLAT

0			

_____ Ft. from N. Line

330 Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

COMPLETED

Location _____

Rig up _____

Drilling and Remarks:

Sil 3321
Pay 3351-54
2000 acid
Pay 987

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth 3354

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

AUG 12 1936 19

S. J. LEWIS

Scout

Handwritten signature

Returned	<i>[Signature]</i>
Cards	<i>[Signature]</i>
Tracing	<i>[Signature]</i>
France Map	<i>[Signature]</i>
Scarborough Map	<i>[Signature]</i>
Moody Map	<i>[Signature]</i>
Scarborough Flat Book	
Moody Flat Book	