


Section 22 Township 19 Range 11-W

Well No. #1 Hirsch

Company B & B



Sec. 22 Twp. 19 R. 11E

Well No. #1 Hirsch Farm

B & B Company

B & B Contractor


990' Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330' Ft. from W. Line

SW NW NE



1950

Elev 1777

REPORT

5/10

Spud 5-7-50

8" @ 220'

WOC

5/24

8" @ 220

Heebner 2910

Br lime 3028

Lans 3050

DST 3084-3110

rec 30' GCM

Cong 3323

Arb 3352

TD 3359

D&A

ABANDONED

721838

Map No. _____ Sec. 22 Twp. 19 R. 11Well No. 1 Hirsch

_____ B & B _____ Company

_____ B & B _____ Contractor

S¹ NW NE

SECTION PLAT

990 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

Barton

Location _____

Rig up _____

Drilling and Remarks:

Spud 5-7-50

8" @ 220

WOC

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

MAY 10 1950

19

J. E. TYRA Scout

RECEIVED

REPORT

Scout Cards
 Land-Small Map
 Land-Wall Map
 Tracings
 France Map
 Pierce Map
 Misc.

3
 MAR 15 1950

Kansas

Map No. _____ Sec. 22 Twp. 19 R. 11Well No. 1 HirschB & B Company


Contractor

SW NW NE

E1.1777
SECTION PLAT990 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

Barton

Location _____

Rig up _____

Drilling and Remarks:

8" C 220
 Heebner 2910
 Bu line 3028
 Lane. 3050
 DST 3084-3110
 Rec 30' gem
 Cong. 3323

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

MAY 24 1950

19

J. E. TYRA

Scout



JUN 5 - 1950

- Scout Cards SW
- Land Small Map S
- Land Wall Map
- Tracings
- France Map
- Pierce Map
- Misc.

at. 3352
FD. 3359
D + A