







BEE FORMATION TESTING CO.

P. O. BOX 491

GREAT BEND, KANSAS

N^o 1671DATE April-19-1957-CUSTOMER'S
ORDER NO. _____NAME OF COMPANY Chas. Hulme-

ADDRESS TO MAIL INVOICE _____


ADDRESS TO MAIL PRESSURE CHARTS Gt. Bend-LEASE Beiwicks WELL NO. 3 COUNTY Barton STATE Ks.TESTER JAH.APPROVED Charles W. SteincampDRILL STEM TEST NO. 1 SUCCESSFUL NO. 1 MIS-RUN NO. _____ FORMATION TESTED ARB.SIZE HOLE 7 $\frac{7}{8}$ TOOL JT. 4 $\frac{1}{2}$ Fh.RUBBER SIZE 6 $\frac{3}{4}$ x 2 $\frac{1}{8}$ x 30. TEST TOOL SIZE 4 $\frac{5}{8}$ x $\frac{1}{4}$ PACKER SET AT 3441- & 3435. ANCHOR SIZE 4 $\frac{1}{2}$ TOTAL DEPTH WELL 3448 LENGTH ANCHOR 7 ft.PRESSURE RECORDER CAP. 3000 - 3500 DRILL PIPE RUN: DRY all WITH FLUID _____

RESULTS:

PACKER SET 9:20 A. M. TOOL OPEN 9:24 M. TOOL OPEN 22 min - HRS.BLOW Weak for 10 min -RECOVERY 15 ft Rotary Mud.SHUT IN PRESSURE TIME 15 min - MUD WT. 10 $\frac{4}{10}$ VIS. 40 WATER LOSS 10 $\frac{8}{100}$ BHP 0 IFP 0 FFP 0 HYDROSTATIC HEAD 1800EXTRA EQUIPMENT None JARS _____ NO. _____ SIZE _____OPERATOR TIME 8 hrs. TOOL RENTAL TIME _____

BEE FORMATION TESTING CO.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE PARTY FOR WHOM A TEST IS MADE, OR FROM ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH OR IN THE COURSE OF THE USE OF ITS EQUIPMENT, ALL OF WHICH LOSS OR DAMAGE IS ASSUMED BY THE CUSTOMER. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT THE COST OF THE PARTY FOR WHOM TEST IS MADE.



BEE FORMATION TESTING CO.

P. O. BOX 491

GREAT BEND, KANSAS

DATE 4-19-57N^o 1672CUSTOMER'S
ORDER NO. _____NAME OF COMPANY Chas Hulme

ADDRESS TO MAIL INVOICE _____

ADDRESS TO MAIL PRESSURE CHARTS _____

LEASE LeiwicksWELL NO. 3COUNTY BartonSTATE Ks.TESTER JDBAPPROVED Charles W. SteincampDRILL STEM TEST NO. 2

SUCCESSFUL NO. _____

MIS-RUN NO. _____

FORMATION TESTED Ark.SIZE HOLE 7 7/8TOOL JT. 4 1/2 Fh.RUBBER SIZE 6 3/4 x 30 x 2 7/8TEST TOOL SIZE 4 5/8PACKER SET AT 34493449ANCHOR SIZE 4 1/2TOTAL DEPTH WELL 3456LENGTH ANCHOR 7'PRESSURE RECORDER CAP. 3000-3500DRILL PIPE RUN: DRY all

WITH FLUID _____

RESULTS:

PACKER SET _____

4:00 P.

M. TOOL OPEN _____

4:06 P.

M. TOOL OPEN _____

20

min.

HRS.

BLOW _____

Weak 3 min Blow.

RECOVERY _____

12 ft Rotary mud


SHUT IN PRESSURE TIME _____


15.MUD WT. 10 1/2VIS. 40WATER LOSS 10 8/10BHP 0IFP 0FFP 0HYDROSTATIC HEAD 1800EXTRA EQUIPMENT Jars + Safety JointJARS SR Bowen NO. 183SIZE 3 1/2 Fh.OPERATOR TIME 8

TOOL RENTAL TIME _____

BEE FORMATION TESTING CO.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE PARTY FOR WHOM A TEST IS MADE, OR FROM ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH OR IN THE COURSE OF THE USE OF ITS EQUIPMENT, ALL OF WHICH LOSS OR DAMAGE IS ASSUMED BY THE CUSTOMER. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT THE COST OF THE PARTY FOR WHOM TEST IS MADE.





BEE FORMATION TESTING CO.

P. O. BOX 491

DATE 4-19-57GREAT BEND, KANSAS NN^o 1673CUSTOMER'S
ORDER NO. _____NAME OF COMPANY Chas Hulme

ADDRESS TO MAIL INVOICE _____

ADDRESS TO MAIL PRESSURE CHARTS _____


LEASE Heintz WELL NO. 3 COUNTY Barton STATE KsTESTER Jim APPROVED Charles W. StencampDRILL STEM TEST NO. 3 SUCCESSFUL NO. _____ MIS-RUN NO. _____ FORMATION TESTED ArbSIZE HOLE 7 7/8 TOOL JT. 4 1/2 F.H.RUBBER SIZE 6 3/4 x 30 x 2 7/8 TEST TOOL SIZE 4 5/8PACKER SET AT 3456 ANCHOR SIZE 4 1/2TOTAL DEPTH WELL 3466 LENGTH ANCHOR 10'PRESSURE RECORDER CAP. 3000-3500 DRILL PIPE RUN: DRY all WITH FLUID _____

RESULTS:

PACKER SET 11:45 M. TOOL OPEN 11:48 M. TOOL OPEN 15 min. HRS.BLOW Weak 2 min.RECOVERY 10' Rotary mud-SHUT IN PRESSURE TIME 15 MUD WT. 10 7 VIS. 40 WATER LOSS 10 8/cc.BHP 500 IFP 0 FFP 0 HYDROSTATIC HEAD 1825-EXTRA EQUIPMENT Jan + Safety Jt. JARS SR Bowen NO. 183 SIZE 3 1/2 Fh.OPERATOR TIME 8 TOOL RENTAL TIME _____

BEE FORMATION TESTING CO.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE PARTY FOR WHOM A TEST IS MADE, OR FROM ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH OR IN THE COURSE OF THE USE OF ITS EQUIPMENT, ALL OF WHICH LOSS OR DAMAGE IS ASSUMED BY THE CUSTOMER. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT THE COST OF THE PARTY FOR WHOM TEST IS MADE.



BEE FORMATION TESTING CO.

P. O. BOX 491

N^o 1674DATE 4-20-57GREAT BEND, KANSAS 2CUSTOMER'S
ORDER NO. _____NAME OF COMPANY Chas Hulme.ADDRESS TO MAIL INVOICE Gt. Bend.ADDRESS TO MAIL PRESSURE CHARTS Ks.LEASE Geiwicks. WELL NO. 3 COUNTY Barton STATE Ks.TESTER JPH. APPROVED Charles W. SteincampDRILL STEM TEST NO. 4 SUCCESSFUL NO. 4 MIS-RUN NO. _____ FORMATION TESTED ARB.SIZE HOLE 7 7/8 TOOL JT. 4 1/2 F.h.RUBBER SIZE 6 3/4 x 30 x 2 7/8 TEST TOOL SIZE 4 5/8PACKER SET AT 3466 ANCHOR SIZE 4 1/2TOTAL DEPTH WELL 3476 LENGTH ANCHOR 10PRESSURE RECORDER CAP. 3000 - 3500 DRILL PIPE RUN: DRY all WITH FLUID _____

RESULTS:

PACKER SET 7:30 M. TOOL OPEN 7:34 M. TOOL OPEN 25 min HRS.BLOW Weak Intermittian For 10 min - (Flush Tools)RECOVERY 30 ft. Slightly oil speck mud-SHUT IN PRESSURE TIME 25 min - MUD WT. 10 4 VIS. 40 WATER LOSS 10 8/10BHP 850 # IFP 0 FFP 0 HYDROSTATIC HEAD 1825 -EXTRA EQUIPMENT para + Safety JARS SR Bowen NO. 183 SIZE 3 1/2 F.h.OPERATOR TIME 8 hrs - TOOL RENTAL TIME _____

BEE FORMATION TESTING CO.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE PARTY FOR WHOM A TEST IS MADE, OR FROM ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH OR IN THE COURSE OF THE USE OF ITS EQUIPMENT, ALL OF WHICH LOSS OR DAMAGE IS ASSUMED BY THE CUSTOMER. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT THE COST OF THE PARTY FOR WHOM TEST IS MADE.