



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED
OCT 25 2010

Test Ticket

NO. 040012 14958

Well Name & No. Ronald-Brian B#1-10 Test No. 1 Date 10-20-10
 Company AMERICA WARRIOR INC Elevation 2345 KB 2334 GL
 Address Harley Sayers PO Box 399 Garden City KS 67846-0399
 Co. Rep / Geo. Harley Sayers Rig Duke 5
 Location: Sec. 10 Twp. 21S Rge. 25W Co. Hodgeman State KS

Interval Tested 4454-4462 Zone Tested Miss
 Anchor Length 8' Drill Pipe Run 4093 Mud Wt. 9.2
 Top Packer Depth 4449 Drill Collars Run 348.63 Vis 65
 Bottom Packer Depth 4454 Wt. Pipe Run 0 WL 14
 Total Depth 4462 Chlorides 4900 ppm System LCM TR

Blow Description IF: Weak 2 inch
IS: No Return
FS: Weak, Surface
FS: No Return

Rec	Feet of	%gas	%oil	%water	%mud
<u>125</u>	<u>MW</u>				
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 125' BHT 122 Gravity API RW .50 @ 50° F Chlorides 19000 ppm
 (A) Initial Hydrostatic 2220 Test 1225 T-On Location 20.48
 (B) First Initial Flow 16 Jars 250 T-Started 257
 (C) First Final Flow 46 Safety Joint 75 T-Open 0020
 (D) Initial Shut-In 1322 Circ Sub _____ T-Pulled 0250
 (E) Second Initial Flow 50 Hourly Standby _____ T-Out 0458
 (F) Second Final Flow 78 Mileage 128 RT 100' Comments _____
 (G) Final Shut-In 1309 Sampler _____
 (H) Final Hydrostatic 2150 Straddle _____ Ruined Shale Packer _____
 Shale Packer _____ Ruined Packer _____
 Extra Packer _____ Extra Copies _____
 Extra Recorder _____ Sub Total 0
 Day Standby _____ Total 1710'
 Accessibility _____ MP/DST Disc't _____

Initial Open 30
 Initial Shut-In 30 45
 Final Flow 30
 Final Shut-In 45
 Sub Total 1710'

Approved By _____ Our Representative [Signature]
 Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.