



**TRIBOLITE
TESTING INC.**

P.O. Box 1733 • Hays, Kansas 67601

RECEIVED
OCT 14 2011

Test Ticket

NO. 43995 16439

Well Name & No. Herman 1-24 Test No. 1 Date 10/11/11
Company American Warrior Inc Elevation 2418 KB 2407 GL
Address PO Box 399 Garden City, KS 67846
Co. Rep / Geo. Harley Sayles Rig Duke 5
Location: Sec. 24 Twp. 22S Rge. 22W Co. Ford State KS

Interval Tested 5030 - 5041 Zone Tested Mississippi
Anchor Length 11 Drill Pipe Run 4704 Mud Wt. 9.4
Top Packer Depth 5025 Drill Collars Run 303 Vis 54
Bottom Packer Depth 5030 Wt. Pipe Run 0 WL 11.6
Total Depth 5041 Chlorides 9100 ppm System LCM 1

Blow Description IF: Strong Blow, BOB in 3 minutes

ISI: Blowback Built to 2 inches

FF: Strong Blow, BOB in 4 minutes

ESI: Blowback Built to 1 inch

Rec	Feet of	%gas	%oil	%water	%mud
<u>2711</u>	<u>GIP</u>				
<u>97</u>	<u>GOWCM</u>	<u>10</u>	<u>10</u>	<u>30</u>	<u>50</u>
<u>62</u>	<u>OMCW</u>		<u>5</u>	<u>81</u>	<u>14</u>
<u>179</u>	<u>water</u>				

Rec Total 388 BHT 126° Gravity N/C API RW .19 @ 70 °F Chlorides 70000 ppm

(A) Initial Hydrostatic 2628

(B) First Initial Flow 27

(C) First Final Flow 94

(D) Initial Shut-In 1233

(E) Second Initial Flow 98

(F) Second Final Flow 152

(G) Final Shut-In 1273

(H) Final Hydrostatic 2469

Initial Open 30

Initial Shut-In 45

Final Flow 60

Final Shut-In 90

☒ Test 1325

☒ Jars 250

☒ Safety Joint 75

☐ Circ Sub

☒ Hourly Standby 3 1/2 hrs 800

☒ Mileage (110) 154

☐ Sampler

☐ Straddle

☐ Shale Packer

☐ Extra Packer

☐ Extra Recorder

☐ Day Standby

☐ Accessibility

Sub Total 2154

T-On Location 23:00 11hrs

T-Started 64:49

T-Open 07:06

T-Pulled 10:54

T-Out 1323

Comments

☐ Ruined Shale Packer

☐ Ruined Packer

☐ Extra Copies

Sub Total 8

Total 2154

MP/DST Disc't

Approved By

Our Representative

Tribolite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.