



TRIBOLITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

OCT 13 2010

NO. 040284 14890

Well Name & No. Damme #42 Test No. 1 Date 10-8-10
Company Haitman Oil Co. Inc. Elevation 2895 KB 2885 GL
Address 10500 E Berkeley Sq. PKWY Ste. 100 Wichita KS 67206
Co. Rep / Geo. Steve Murphy Rig H2 #1
Location: Sec. 28 Twp. 22 Rge. 33 Co. Finney State KS

Interval Tested 4628 - 4693 Zone Tested Morrow Sand
Anchor Length 65 Drill Pipe Run 4331 Mud Wt. 9.3
Top Packer Depth 4623 Drill Collars Run 279 Vis 52
Bottom Packer Depth 4628 Wt. Pipe Run 0 WL 8.8
Total Depth 4693 Chlorides 2800 ppm System LCM 3#
Blow Description IF - Weak building blow 5" in bucket.
ISI - No blow back.
FF - Weak building blow 2" in bucket.
FSI -

Rec	Feet of	%gas	%oil	%water	%mud
300	GIP				
250	06cm	5	5	0	90

Rec Total	BHT	Gravity	API RW	@	°F	Chlorides	ppm
(A) Initial Hydrostatic	2112	☐ Test	1225			T-On Location	545 Am
(B) First Initial Flow	45	☐ Jars	250			T-Started	615 Am
(C) First Final Flow	102	☐ Safety Joint	75			T-Open	800 AM
(D) Initial Shut-In	381	☐ Circ Sub				T-Pulled	1115 Am
(E) Second Initial Flow	111	☐ Hourly Standby				T-Out	100 PM
(F) Second Final Flow	149	☐ Mileage	WRT 80'			Comments	
(G) Final Shut-In	380	☐ Sampler					
(H) Final Hydrostatic	2176	☐ Straddle				☐ Ruined Shale Packer	

Initial Open	Initial Shut-In	Final Flow	Final Shut-In	Sub Total	Total	MP/DST Disc't
30	45	45	60	0	2030-	

Approved By Steve Murphy Our Representative 1880
Tribolite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.