

DRILLING TIME

1995

Continental #1 Gleason
Section 5, Township 24 South, Range 21 West, Hodgeman County, Kansas.

3000 to 3010	11-10-6-8-6 ³⁸⁻¹⁰	grease up & conn. @ 3008'	
3020	11-9-13-12-10 ¹⁰⁻²⁰		
3030	12-4-9-10-8 ²⁰⁻³⁰		
3040	8-7-7-14-8 ²⁰⁻⁴⁰	6 min. conn. @ 3038'	
3050	6-10-12-15-21 ⁴⁰⁻⁵⁰		
3060	16-16-25-6-8 ⁵⁰⁻⁶⁰	pick up out of hole to clean bit - 10 minutes over @ 3058'	
3070	9-8-9-6-8 ⁶⁰⁻⁷⁰	8 minutes conn. @ 3068'	
3080	6-8-8-4-5 ⁷⁰⁻⁸⁰		
3090	3-4-4-5-7 ⁸⁰⁻⁹⁰		
3100	3-8-8-8-8 ⁹⁰⁻¹⁰⁰		
3110	8-9-9-8-10		
3120	10-10-10	down 10 minutes @ 3116'	
3230	3240	14-17	
3250	19-25-23-12-10	Trip, conn. and work on rig @ 3244'	
3260	11-13-17-11-12		
3270	11-12-14-8-11		
3280	10-10-11-10-10	conn. @ 3276'	
3290	7-8-7-8-5		
3300	5-7-5-5-8		
3310	3-6-5-10-10	Syfo @ 3308'	
3320	5-2-4-4-5		
3330	5-7-8-6-9		
3340	5-7-7-7-7	conn. @ 3338'	
3350	8-8-10-7-8		
3360	8-8-9-8-9		
3370	8-7-9-10-10	conn. @ 3368'	
3380	10-12-13-10-10		
3390	10-15-15-16-14		
3400	14-13-13-12-12		
3410	12-14-12-11-11		
3420	11-12-12-13-13		
3430	15-15-12-11-10	10 minutes conn. @ 3324'	
3440	10-11-11-13-14		
3450	14-15-16-16-20		
3460	22-20-21-18-17	20 minutes conn. & grease up rig @ 3456'	
3470	19-19-15-14-15	mud vis. 39 @ 3462'	
3480	15-10-8-15-12-22		
3490	18-17-20-12-12	conn. & grease @ 3486' - vis 38 @ 3488'	
3500	12-17-14-17-14	mud vis. 39 @ 3500'	
3510	11-10-10-13-10	Down 15 minutes @ 3506' - 8:35 to 10:55 trip @ 3508'	
3520	11-12-12-12-13		
3530	9-6-10-7-9		
3540	9-9-9-7-10		
3550	12-10-10-11-10		

3550 to 3560	11-11-10-11-10	
3570	7-10-10-15-10	conn. @ 3568'
3580	10-12-10-10-10	
3590	11-12-14-12-12	
3600	13-13-12-12-13	conn. & oil up 16 minutes @ 3594'
3610	13-13-10-7-8	
3620	11-6-8-11-14	
3630	12-11-2-2-2	conn. @ 3624' and break 3625' to 3635'
3640	4-5-7-8-9	
3650	12-15-14-12-13	
3660	13-24-no time-22-18	conn. & grease rig @ 3656'
3670	12-14-15-21-10	
3680	8-8-3-5-2	10 points WT @ 3672' - break 3676'
3690	4-5-7-5-5	connection @ 3686'
3700	5-10-15-13-12	
3710	8-4-4-18-16	conn. @ 3716'
3720	7-8-15-12-18	down working on pump @ 3728'
3730	10-10-10-5-7	
3740	8-9-23-23-15	trip & working on pump @ 3742'
3750	12-7-8-15-7	
3760	8-10-11-14-10	
3770	10-12-15-12-13	
3780	14-16-12-10-5	conn. 15 minutes & oil up @ 3774'
3790	8-10-9-6-5	
3800	8-10-10-12-13	
3810	21-14-12-14-26	conn. 10 minutes @ 3806'
3820	23-19-18-23-25	
3830	25-28-26-17-14	10 points WT @ 3828' - mud 33 @ 3830'
3840	15-15-17-23-21	conn. 8 min. & grease @ 3838'
3850	25-29-34-23-10	15 points @ 3842' - mud vis. 33 @ 3850'
3860	17-9-9-13-20	15 to 20 points @ 3860'
3870	12-14-13-12-10	mud 34 @ 3862' - conn. 11 min. @ 3868'
3880	15-10-9-11-8	
3890	10-10-21-18-5	down @ 3884' - trip @ 3890'
3900	5-5-10-6-8	conn. @ 3894' - down 5 min. @ 3896'
3910	6-6-6-8-5	
3920	5-5-5-5-5	
3930	5-7-4-6-6	
3940	7-10-10-10-11	
3950	9-5-5-20-15	20 off oil up @ 3956'
3960	9-6-15-11-10	
3970	10-16-15-12-10	
3980	6-24-24-20-25	
3990	29-20-20-24-23	conn. 13 min. @ 3984'
4000	18-21-22-30-22	
4010	17 22 23 23 20	mud vis. 38 @ 4008'
4020	22 20 16 13 15	error on Kelly @ 4016'
4030	16 17 19 23 27	
4040	20 30-34-22-24	trip @ 4035' - work on pits 19 min. @ 4040'

H. G. WRIGHT DONATION

4040 to 4050	16-30-19-31-16	conn. @ 4048'
4060	25-18-23-30-31	
4070	33-35-30-30-10	Trip @ 4070'
4080	10-10-10-18-16	
4090	19-20-17-18-20	
4100	10-20-27-25-15	
4110	13-15-25-22-48	conn 10 min. & grease rig @ 4108'
4120	7-16-14-14-12	
4130	9-11-10-12-20	
4140	19-14-11-11-20	2 min. conn. @ 4136'
4150	18-13-13-15-13	
4160	13-14-13-13-15	down 20 min. @ 4160'
4170	12-10-13-14-21	conn. @ 4164'
4180	27-27-33-15-32	
4190	30-28-25-20-15	
4200	5-3-3-9-26	conn. @ 4194'
4210	27-28-33-30-30	
4220	30-30-25-13-32	
4230	30-20-15-40-37	conn. @ 4226'
4240	10-11-4-3-3	4 min. down @ 4234'-circ. 1 1/2 hrs. @ 4240'
4250	10-2-2-3-2	
4260	2-2-2-2-3	
4270	2-3-no time-8-7	connection 10' too long - also error made in adding joint to tally board. @ 4266'
4280	18-18-12-20-20	
4290	20-19-no time-30-23	out of water @ 4286'
4300	17-20-25-20-18	
4310	18-19-15-20-20	
4320	20-22-20-21-20	
4330	20-17-20-20-no time	conn. @ 3226' - trip and grease @ 3230'
4340	18-25-17-26-26	
4350	22-29-25-25-13	
4360	16-18-20-19-19	conn. 18 min. @ 4356'
4370	15-20-19-18-24	
4380	26-32-32-27-28	
4390	18-14-13-24-28	conn, down, & grease 18 min. @ 4386'
4400	29-15-18-23-23	
4410	17-26-20-15-20	working on pump @ 4408'
4420	25-24-16-12-25	conn. @ 4416'
4430	24-24-27-28-23	
4440	25-30-25-28-no time	working on pump @ 4434'
4450	no time-25-27-12-19	change time & oil rig @ 4442'
4460	16-24-36-41-30	
4470	33-22-34-29-27	
4480	27-29-22-27-28	conn. & work on pump & oil rig 40 min. @ 4478' - out of hole @ 4480'
4490	16-15-16-22-20	
4500	20-20-17-16-11	
4510	9-11-7-14-13-12-9-8-9-11	cir tes @ 4506'
4520	16-25-15-21-15-1	
4530	13-13-11-11-16-1	

J. G. WRIGHT DONATION.

4530 to 4540 15-15-25-17-18-14-17-14-15-10
 4550 12-12-11-12-13-11-14-17-20-17
 4560 21-19-18-18-18-17-16-21-17-18
 4570 18-23-17-18-20-18-20-9-12-12
 4580 13-13-10-10-15-15-16-19-20-23
 4590 20-20-23-21-16-18-21-19-24-18
 4600 18-18-22-16-20-16-17-17-13-14

4610 14-20-22-20-11-27-23-9-20 15
 4620 11-15-14-14-17-11-13-14-16-18
 4630 18-20-20-25-21-21-20-23-16-20
 4640 20-22-20-20-22-19-19-21-21-18
 4650 17-17-14-23-29-17-21-20-20
 4660 18-19-15-16-14-14-14-14-14-13
 4670 17-22-25-5-8-8-10-10-20-10

4680 11-12-12-10-11-11-7-6-10-10
 4690 11-7-3-5-4-8-17-17-14-16
 CORED 4668' to 4681'
 CORED 4681' to 4691'

4700 20-17-7-13-10-15-14-14-13-7
 4710 10-12-15-14-24-15-17-18-10-10
 4720 10-9-14-10-12-10-7-3-5-4

4730 6-20-12-4-5-4-5-3-4-5

4737 4-6-10-12-10-17-20-
 CORRECTION 4715' = 4705'

4727 to 4728 5
 4730 10-15
 4740 15-9-10-10-15-15-17-15-14-10
 4750 10-13-15-24-18-18-15-20-20-23
 4760 20-15-12-18-12-13-15-15-20-18
 4770 22-16-28-22-10-19-20-16-10-14
 4780 13-12-16-15-15-14-14-17-22-18
 4790 22-16-19-20-20-20-15-20-23-24
 4800 20-18-23-20-20-23-15-10-15-20
 4810 10-23-10-7-5-6-6-14-14-14
 4820 14-12-15-12-19-27-25-no time-42-40

4830 17-32-33-22-20-27-37-38-73-7

4840 3-5-5-5-5-5-6-5-5-5 +
 4850 10-14-14-13-11-10-14-11-11-12
 4860 7-6-4-6-5-5-5-5-6-7
 4870 10-7-7-8-8-12-10-13-13-14
 4880 12-14-13-14-13-12-12-8-10 5
 4890 8-10-12-11-11-11-14-no time-12-13

4900 13-13-12-8-17-15-11-6-7-11

conn. @ 4536'

oil up & conn. @ 4567'

1 hr. work on pump & conn.
 4596'

conn. 8 min. @ 4628'
 (partly rough @ 4640-43')
 corrected back 1' - 49548
 circ. 1 1/2' @ 4656' also
 correction of 1' & circ.
 1 hr. @ 4658'
 circ. 1 1/2' @ 4662'
 rough @ 4654 - 4658 - 4663
 and from 4691 to 4705'
 partly rough 4709 & 10'
 rough from 4711 to 13'

O.B. bit 23 - oiling up &
 conn. trip @ 4716'
 circ. 2 hrs. @ 4721'
 rough, down 4 min. @ 4738'
 circ. 2 hrs. @ 4733'

conn. & checking @ 4738'

grease rig @ 4760'
 conn. 16 min. @ 4768'

working on mud line @ 4780
 conn. @ 4797'
 circ. 2 hrs. @ 4808'
 grip @ 4817' - grease rig
 @ 4818' (new bit 4718-29)
 conn & stir pits 10 min.
 and trip @ 3829'
 circ. 2 hrs. @ 4841'

grease rig & conn. 10 min.
 @ 4889'
 rough chert 4894-99'

G. WRIGHT

4900 to 4910 11-18-18-5-5-7-6-7-10-6

4920 6-10-10-10-10-10-12-12-11-10
 4930 15-10-8-12-15-21-19-20-18-19
 4940 18-21-21-23-25-22-22-24-18-21
 4950 20-23-20-24-20-25-20-23-25-25
 4960 20-23-14-14-20-17-23-16-26-17
 4970 23-12-11-12-12-10-13-14-13-15
 4980 15-12-15-17-20-18-17-12-21-20
 4990 25-9-5-10-10-12-14-12-17-17
 5000 19-15-10-10-15-15-17-20-26-17
 5010 15-18-16-16-20-17-20-10-15-10
 5020 13-13-12-17-18-24-16-13-17-15
 5030 19-19-12-22-18-20-25-16-18-26
 5040 15-20-20-23-28-38-16-21-22-21

5050 22-23-16-18-11-27-29-18-12-18

5060 18-15-17-14-10-16-11-15-12-13

5070 14-11-10-11-14-15-17-15-15-11
 5080 13-10-9-11-13-14-17-13-20-13
 5085 15-12-23-20-21

trip @ 4904' - rough from 4904 to 4911'

conn. @ 4922'

out of hole OB 6:54
greasing up 4972'
down @ 4982'

rough 5008 to 10'
conn. @ 5012'

rough @ 5032 & 33' - no
drilling mud 5034 to 36'
conn. & check rig 9 min. @
5042' - rough 5049 & 5050'
rough 5053, 5059 & 60'
trip @ 5053'

conn. @ 5073'

TOTAL DEPTH 5085'

I. G. WRIGHT DONATION

I. G. WRIGHT

1995