

Simpson 4020 stain
and odor 4020-27

P.S.T. 4020-27 open 25
min, rec 95' mud + wtr

arb 4/25

Perf 12/4012-14 no shows
593. 88 perf.

report 24/3997-4002

P 15 B0 + 180 water P.D.

Scout Cards

Land Small Map

Land Wall Map

Tracings

France Map

Pierce Map

Misc.

Earth
3

MAR 22 1950

Kansas

Map No. _____ Sec. 14 Twp. 26 R. 6WWell No. 1 Graber

Cities Service

Company


Contractor

NW NE

FI. 1530
SECTION PLAT330 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

Reno County

Location _____

Rig up _____

Drilling and Remarks:

7' @ 284

5" @ 4105

Loss 2955

Miss 3625

D.S.T. 3634-45 mc

180' oil, 20' oil cut

mud (over)

Date

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth 4166

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

MAR 15 1950

19

J. E. TYRA

Scout