

Sec. 3 Twp. 31 R. 34W

Well No. #1 Baughman "D" Farm

Cities Service Company

Hugoton


100 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

100 Ft. from W. Line

NW SE



1947

REPORT

8/27 Location

9/3 "

9/10 "

9/17 "

9/24 "

10/1 8" @ 600'

10/8 TD 2777'
5" @ 2776'

10/15 "

10/22 "

10/29 "

11/5 180 shots 2686-2722'
105 " 2634-55
160 " 2582-2614 fsg.

11/12 50 shots 2552-62' - 13500 acid.

11/19 "

11/25 "

12/3 "

12/10 "

1947

12/17 5" @ 2776
Perf. 22500 acid
28,500,000 Gas
412# RPr
TD 2777'

COMPLETED

Map No. _____ Sec. 3 Twp. 31 R. 34W

Well No. 1 Baughman "D"

Cities Service Company

FIRST REPORT

Contractor

NW SE


SECTION PLAT

100 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

100 Ft. from W. Line



Seward County

Location X

Rig up _____

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

AUG 27 1947 19

S. J. LEWIS Scout

no map

Type	
Cards	<i>Ruth</i>
Tracing	
France Map	
Scarborough Map	<i>Q</i>
Pierce Map	
Geological Dept.	
Pierce Plat Book	

Map No. _____ Sec. 3 Twp. 31 R. 34W

Well No. 1 Baughman "D"

Cities Service Company

COMPLETE Contractor

NW SE

L712922
SECTION PLAT

100 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

100 Ft. from W. Line

		o	

Seward County

Location _____

Rig up _____

Drilling and Remarks:

5" C2776

Prof.

22,500 acid

28,500,000 gas

H12 # R B

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth 2777

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

DEC 17 1947 19

S. J. LEWIS

Scout

[Handwritten signature]

Misc. Sm.	S
Cards	<i>Elaine</i>
Tracing	
France (c)	
Scarborough Map	<i>X</i>
Pierce Map	<i>X</i>
Geological Dept.	
Pierce Plat Book	

[Handwritten signature]