

KANSAS


Barber

FORM 51 5M PETROL

Section 34 Township 31 Range 11-W

Well No. #1 Davenport

Company Great Lakes Carbon



KANSAS

FORM 252-A
SM 9-43 GASS


Barber

Sec. 34 Twp. 31 R. 11 W

Well No. #1 Davenport Farm

Great Lakes Carbon Company

NORTH



SOUTH

Ft. from N. Line

330

660

Ft. from S. Line

330

660

Ft. from E. Line

Ft. from W. Line

Elev. 1567

1943

R E P O R T

12-8 Skelly farm-out

12-15 Location

12/22 "

12/29 Rotary

1944

1-5 "

1-12 Drlg 200'

1/19 10" @ 354

WOC.

1/26 Drlg. 2470'

2/2 Topeka 2900?

Drlg. 3744

2/8 Miss 4395

Drlg. 4400

2/16 Miss

TD 4445


ABANDONED

KANSAS

Map No. 61 Sec. 34 Twp. 31 R. 11WWell No. 1 DavenportGreat Lakes Carbon CompanyFIRST REPORT Contractor

C SE SW

SECTION PLAT

 Ft. from N. Line660 Ft. from S. Line660 Ft. from E. Line Ft. from W. Line

Wild cat

Location XRig up

Drilling and Remarks:

Skelly farm-out

RECORD

Cased in., ft.Sand Gas Oil Total Depth

PRODUCTION

1st 24 hrs. Nat. 1st 24 hrs. after shot Gas Cu. Ft.Dry Hole Abandoned


Date

DEC 8 1943 19S. J. LEWIS Scout

Map No. 51 Sec. 34 Twp. 31 R. 11WWell No. 1 DavenportGreat Lakes Carbon Company**CORRECTION**

Contractor

SE SW

SECTION PLAT

Ft. from N. Line

330

Ft. from S. Line

330

Ft. from E. Line

Ft. from W. Line

Wildcat

Location _____

Rig up _____

Drilling and Remarks:

Reported**C SE SW****RECORD**

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned ^{ff} _____

Date

DEC 15 1943

19

S. J. LEWIS


Scout

KANSAS

Map No. 61 Sec. 34 Twp. 31 R. 11WWell No. 1 DavenportGreat Lakes Carbon CompanyABANDONED Contractor

SE SW

SECTION PLAT

 Ft. from N. Line330 Ft. from S. Line330 Ft. from E. Line Ft. from W. Line

Wildcat

Location Rig up

Drilling and Remarks:

Miss 4395

RECORD

Cased in., ft.Sand Gas Oil Total Depth 4445

PRODUCTION

1st 24 hrs. Nat. 1st 24 hrs. after shot Gas Cu. Ft.Dry Hole Abandoned

Date

FEB 16 1944 19 S. J. LEWIS Scout