

Morton

KANSAS

SECTION 15 TOWNSHIP 33S RANGE 40W

WELL NO. #2 Hayward

COMPANY Panhandle Eastern

		NORTH				SE NW SW		
WEST								EAST
		SOUTH						

12

CORRECTION

S-513-A

CO. Morton ELEV. 3500SEC. 15 TWP. 33 RGE. 40WCOMPANY Panhandle Eastern 2-15

BANDONED

JAN 8 '58

FARM HaywardLOC. SE NW SWGEOL. XCONTR. Sierra Drlg.POOL WildcatSPUD 11-29-57drlg. 15408" 1619/1750Ø 3170DST 3249-330030" 15' M FPCBHP 480/25" Ø 4

DEC 26 '57

DST 4720-90 43"20' M FPC 25-30 BHP 615/20Ø 5445 JAN 2 '58 DST 5555-5615 30" 15' M FPCBHP 370/20" DST 5653-90 60" 150' SNT 4 gcm3000' gcm FPC 220-1470BHP 1570/20" TD 5855run log JAN 8 '58 Log TopsKv 1 2309 Win 2373Twanda 2439 Wab 3043TP 3280 Grwood 3668Lsg 3887 Marm 4606Ce 4763 Movsh 5259sd 5552-66 sd 5582-94Keys 5652-5700 Miss 5748

DIA

WILDCAT

S-513-A

CO. Morton ELEV. _____
 SEC. 15 TWP. 33 RGE. LOW
 COMPANY Panhandle Eastern 2

FIRST REPORT

USE 4 55

6

FARM Hayward

LOC. SE NW SW

GEOL. _____
 CONTR. Sierra Drlg.
 POOL Wildcat
 SPUD 11-29-57
drlg. 1540

CO

LSE

NO.

SEC.

TWP.

RGE.

1