

PHONE
318 / 624-7340

DEAN'S TESTERS INC.

P. O. BOX 1182
LIBERAL, Ks. 67901

Formation _____ Type Test Hook Straddle Misrun Date June 6, 1981
Anchor Length and Size 23' x 4 1/2" Total Depth 6100'
Packer Depths 4372' & 4377' Below Straddle 4400'
Equipment Run 3 Packers, Jars, Safety Joint, Circulating sub., Straddle Assembly,
Sidewall Hook Assembly
Lengths: Tool 68' D. P. _____ ID 3.8" Wt. P. _____ ID _____ D. C. 514' ID 2.25"
Mud Type _____ Vis. _____ Wt. _____ Wtr. Loss _____ Cl. _____ ppm
Recorders:
Depth 4383' Make Kuster Cap. 6600 Ser. No. 13199 Inside
Depth 4397' Make Kuster Cap. 7500 Ser. No. 2837 Outside
Depth 4410' Make H & T Cap. 7000 Ser. No. 46 Below Straddle

Pressures:

Tool on Bottom @ _____ M. Initial Hydrostatic _____ psi
Initial Flow _____ Min. IFP _____ psi to _____ psi
Initial Shut-In _____ Min. ISIP _____ psi
Final Flow _____ Min. FFP _____ psi to _____ psi
Final Shut-In _____ Min. FSIP _____ psi
Tool off Bottom @ _____ M. Final Hydrostatic _____ psi Temp. _____

Blow: _____

Recovery: _____

*State Geological Survey
WICHITA, BRANCH*

Gas Flow:

Sampler Data:

Pressure _____ PSI
Gas _____ cu. ft.
Total Fluid _____ cc
Oil _____ cc
Water _____ cc
Mud _____ cc
Oil Gravity _____ @ _____ °F.
Gas/Oil Ratio _____

Remarks:

Packers failed.

Tester Roy Cooper Witnessed by: _____

SEC. 16 TWP. 33S RGE. 32W

COUNTY Seward

STATE Kansas

TICKET NO. 736


First National Oil
OPERATOR

Shirley #1
WELL NAME & NO.

TEST #

4377' - 4400'
TEST INTERVAL

- 736



2837

