

\*\*\*\*

Field Interstate

State Kansas

County Morton

Company J. M. Huber

Farm Block "A"

Well No. 10

Sec. 20 Twp. 34S

Range 43W

fr N fr E fr S fr W

of NE NE

Contractor

Remarks

Comm. 3484 DF 3476 GL Comp. 1-25-56

REV. 12-22-55 T. D. 4224 P. B.

Pay 4165-75

I. R. (BHR) F10 1154 <sup>BOPD</sup> R. P.

Casing Record: 13 3/8 7  
 20 10 3/4 5 1/2 4224/200  
 16 8 5/8 1119/600

Date	Notes	Tops	Surp
NOV 2 1955	<u>LOC</u>		<u>Purdy 4133</u>
NOV 5 1955	✓		<u>LOG TOPS</u>
DEC 7 1955	<u>AIRT</u>		<u>TOPE 2668</u>
DEC 14 1955	✓		<u>Lony 2900</u>
DEC 21 1955	✓		<u>Max fm 4055</u>
28-55	<u>ran 8 7/8 @ 1119/600</u>		<u>Purdy 4130</u>
	<u>WOC</u>		
JAN 4 1955	<u>lost wire 3196-3473</u>		
	<u>lony @ 3926 - NY</u>		
JAN 11	<u>1</u>		
	<u>OST 4130-46 AP 22" 975 1/2" 4"</u>		
	<u>g 2,700 mgf 10" g 3,210 mgf -</u>		
	<u>20" g 3,310 mgf - spray oil &amp; mud</u>		
	<u>22" run 300' oil &amp; 5' FR mud -</u>		
	<u>FP 608-700 BH 1250/20</u>		
	<u>ran el log 4224 RTD</u>		
	<u>set 5 1/2 @ 4224 w/200</u>		
	<u>MILL CO 4195 BR</u>		

2 480  
2 260  
6

~~pg 20 / 4170-75 ran T w ph 4155  
samba well in - 8hr test flo  
176 bbls + no water. sup to pull  
T~~

JAN 18 ~~pg 20 / 4165-70 ran 2" T to 4194  
flo 21 BOPH for 3 1/2 hrs~~

WO T.

JAN 25

Break-test -

Flowed - 1184 BOPD

⌘