

# TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

APR 18 2011

## Test Ticket

NO. 042817

15651

Well Name & No. Becker #1 BY: \_\_\_\_\_ Test No. 1 Date 4/16/11  
 Company Bach, Jason dba Bach Oil Products Elevation 2043 KB 2038 GL \_\_\_\_\_  
 Address PO BOX 723 AIMA NE 68920  
 Co. Rep / Geo. Bob Peterson Rig Martin #16  
 Location: Sec. 30 Twp. 4 Rge. 20w Co. Phillips State KS

Interval Tested 3295-3320 Zone Tested LAC "C"  
 Anchor Length 25 Drill Pipe Run \_\_\_\_\_ Mud Wt. 9  
 Top Packer Depth 3290 Drill Collars Run 30 Vis 56  
 Bottom Packer Depth 3295 Wt. Pipe Run \_\_\_\_\_ WL 8.0  
 Total Depth 3320 Chlorides 800 ppm System \_\_\_\_\_ LCM \_\_\_\_\_  
 Blow Description ZF - Mis-Run

~~Hit~~ Hit & bridge at 1055 ft


Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total \_\_\_\_\_ BHT \_\_\_\_\_ Gravity \_\_\_\_\_ API RW \_\_\_\_\_ @ \_\_\_\_\_ °F Chlorides \_\_\_\_\_ ppm

(A) Initial Hydrostatic \_\_\_\_\_  Test 925- T-On Location 15:45  
 (B) First Initial Flow \_\_\_\_\_  Jars 250- T-Started 15:45  
 (C) First Final Flow \_\_\_\_\_  Safety Joint 75 T-Open ~~15:45~~  
 (D) Initial Shut-In \_\_\_\_\_  Circ Sub \_\_\_\_\_ T-Pulled \_\_\_\_\_  
 (E) Second Initial Flow \_\_\_\_\_  Hourly Standby \_\_\_\_\_ T-Out 17:45  
 (F) Second Final Flow \_\_\_\_\_  Mileage 130 RT - 162.50 Comments HIT & bridge  
 (G) Final Shut-In \_\_\_\_\_  Sampler \_\_\_\_\_  
 (H) Final Hydrostatic \_\_\_\_\_  Straddle \_\_\_\_\_  Ruined Shale Packer \_\_\_\_\_  
 Shale Packer \_\_\_\_\_  Ruined Packer \_\_\_\_\_  
 Initial Open \_\_\_\_\_  Extra Packer \_\_\_\_\_  Extra Copies \_\_\_\_\_  
 Initial Shut-In \_\_\_\_\_  Extra Recorder \_\_\_\_\_ Sub Total 8  
 Final Flow \_\_\_\_\_  Day Standby \_\_\_\_\_ Total 1412.50  
 Final Shut-In \_\_\_\_\_  Accessibility \_\_\_\_\_ MP/DST Disc't \_\_\_\_\_  
 Sub Total 1412.50

Approved By \_\_\_\_\_ Our Representative Bob Peterson

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.



# TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

APR 18 2011

## Test Ticket

NO. 042818

Well Name & No. Becker #1 Test No. 2 Date 4/16/11  
 Company Bach, Jason dba Bach Oil Production Elevation 2043 KB 2098 GL  
 Address PO Box 723 Alma NE 68920  
 Co. Rep / Geo. Bob Peterson Rig Murphy #16  
 Location: Sec. 30 Twp. 4 Rge. 20w Co. Phillips State KS

Interval Tested 3405-3510 Zone Tested LKC "C"  
 Anchor Length 105 Drill Pipe Run \_\_\_\_\_ Mud Wt. 9  
 Top Packer Depth 3400 Drill Collars Run 30 Vis 56  
 Bottom Packer Depth 3405 Wt. Pipe Run \_\_\_\_\_ WL 8.0  
 Total Depth 3510 Chlorides 800 ppm System LCM \_\_\_\_\_

Blow Description IF - 1 3/4 in blow  
ISF - No blow  
PF - 5 in blow  
FSF - No blow

Rec	Feet of	%gas	%oil	%water	%mud
<u>20</u>	<u>MCO</u>	<u>55</u>		<u>45</u>	
<u>60</u>	<u>MCO</u>	<u>70</u>		<u>30</u>	
<u>60</u>	<u>OCM</u>	<u>40</u>		<u>60</u>	
<u>60</u>	<u>SOCM</u>	<u>15</u>		<u>85</u>	
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 200 BHT 100 Gravity \_\_\_\_\_ API RW \_\_\_\_\_ @ \_\_\_\_\_ °F Chlorides \_\_\_\_\_ ppm

(A) Initial Hydrostatic 1668  Test 1125- T-On Location ~~11:30~~ 9:30  
 (B) First Initial Flow 23  Jars 250- T-Started 9:45  
 (C) First Final Flow 94  Safety Joint 75- T-Open 12:22  
 (D) Initial Shut-In 4,020  Circ Sub \_\_\_\_\_ T-Pulled 15:37  
 (E) Second Initial Flow 87  Hourly Standby \_\_\_\_\_ T-Out 17:20  
 (F) Second Final Flow 107  Mileage 130 RT. 1102.50 Comments \_\_\_\_\_  
 (G) Final Shut-In 4,012  Sampler \_\_\_\_\_  
 (H) Final Hydrostatic 4,616  Straddle \_\_\_\_\_  Ruined Shale Packer \_\_\_\_\_  
 Shale Packer \_\_\_\_\_  Ruined Packer \_\_\_\_\_  
 Extra Packer \_\_\_\_\_  Extra Copies \_\_\_\_\_  
 Extra Recorder \_\_\_\_\_ Sub Total 9  
 Day Standby \_\_\_\_\_ Total 11012.50  
 Accessibility \_\_\_\_\_ MP/DST Disc't \_\_\_\_\_  
 Sub Total 11012.50

Approved By \_\_\_\_\_

Our Representative Bob Peterson

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.