## DISTRICT CONSERVATION AGENT'S REPORT

TO:

and 10 sax cement to bottom cellar.	MAR - 7 1951
and 10 sax cement to bottom cellar.	Allen .
and 10 sax cement to bottom cellar.	
·	, , , , , , , , , , , , , , , , , , , ,
15 sax cement, heavy mud to 40°, se	
Pumped hole full rotary mud, set wo	, , , , , , , , , , , , , , , , , , , ,
Casing stuck at 2660', lost 300' of	
Well was completed as to T. D. Comp	· ·
10 3/4" at 206' circulated with cem	• • • • • • • • • • • • • • • • • • • •
(Describe briefly the manner in wh	ich the well was plugged)
Total Depth 3570 Feet.	WPhillips
Field Coun	tw Design
Well No. 2 Lease Ann 1 Operator Honaker Drg Co Addr	1818 Broadway
I have today completed supervision of pl	and a construction of the second seco
lost hole Dry Hole Abandoned Oil Well	SEC, 33 TWP. 1 RGE, 18
	LOCATION NW NW SE
	FILE NO.
	apr.
800 Bitting Building Wichita, Kansas	