4-<u>071091</u>

TO:	API number: 15-153-20,799-00-00
STATE CORPORATION COMMISSION	•
CONSERVATION DIVISION - PLUGGING	<u>NW SW SW</u> /4 SEC. 30 , 01 S, 31 W
200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	feet from S section line
WICHITA, KANSAS 6/202	feet from E section line
Operator license#_5131_	7
operator ricense#_5131_	Lease <u>Wahrman</u> well # <u>1</u>
Operator: Thunderhind Drilling Inc	Country David L
Operator: Thunderbird Drilling, Inc.	County <u>Rawlins</u>
Address: P.O. Box 780407 Wichita, Kansas 67278 Burke B. Krueger	Wall tatal lands and 133,90
Wichita Kangag 67270	Well total depth 4120 feet
Burke B. Krueger	Conductor Pipe: 0 inch 6 0 feet
	Surface pipe 8 5/8 Inch @ 296 feet
Aband. oil well, Gas well, Inp	ut voll cup p c s
	ac well, SWD, D & A _X
Plugging contractor: Abercrombie Drill	ing Tigongo# 20004
JJ w J Little Color Land Color	
Address: Wichita, Kansas 67278	
Company to plug at: Hour: A.M. Day:	27 Month: March Wasse
Day.	27 Month: March Year: 94
Plugging proposal received from: Tony	Martin
JJ J [= P = D = D = D = D = D = D = D = D = D	Mai cii
Company: Abercrombie Drilling	Phone: 216-605-1441
	Fnone
Were: 8 5/8" - 296' S.P. cwc. w/185	
	GVG 60/40 normity - 90 mal
3% C.C. By Allied Cementing Ely 200	<u>sxs. 60/40 pozmix - 2% gel - 2 </u>
38 C.C. By Allied Cementing. Elv. 288	3! - Anhy, 2683! - No girquistion
<u>problems - No arbuckle - Mud condition</u>	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W T. 8 8 -
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 -
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730! - 100 sys. with one
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' -	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate)
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion in	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate)
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' -	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate)
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent?	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X]
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion in	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X]
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Montage 1980 is	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] hth: March , Year: 94
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Drives	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] hth: March , Year: 94
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dr. Pozmix - 6% gel and one sack flocele.	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] hth: March , Year: 94 Circulated hole - spot and
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dripozmix - 6% gel and one sack flocele. displaced all cement through drill pipe	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] hth: March , Year: 94 Circulated hole - spot and
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dripozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement.	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] with: March , Year: 94 illing ordered 190 sxs. 60/40 Circulated hole - spot and with heavy mud between all plugs.
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dripozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement will 3rd. plug at 345' w/40 sxs. cement	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dripozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement will 3rd. plug at 345' w/40 sxs. cement	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dr. pozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement will 3rd. plug at 345' w/40 sxs. cement. 4th. plug at 40' w/10 sxs. cement.	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] with: March , Year: 94 illing ordered 190 sxs. 60/40 Circulated hole - spot and with heavy mud between all plugs. ith 1 sx. flocele.
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dripozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement will 3rd. plug at 345' w/40 sxs. cement	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] with: March , Year: 94 illing ordered 190 sxs. 60/40 Circulated hole - spot and with heavy mud between all plugs. ith 1 sx. flocele.
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dripozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement wide 3rd. plug at 345' w/40 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing.	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dr. pozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement will 3rd. plug at 345' w/40 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing.	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] with: March , Year: 94 illing ordered 190 sxs. 60/40 Circulated hole - spot and with heavy mud between all plugs. ith 1 sx. flocele.
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dr. pozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement will 3rd. plug at 345' w/40 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing.	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] with: March , Year: 94 illing ordered 190 sxs. 60/40 Circulated hole - spot and with heavy mud between all plugs. ith 1 sx. flocele.
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dr. pozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement will 3rd. plug at 345' w/40 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing.	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] with: March , Year: 94 illing ordered 190 sxs. 60/40 Circulated hole - spot and with heavy mud between all plugs. ith 1 sx. flocele.
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dripozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement with 3rd. plug at 345' w/40 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing. Condition of casing(in hole):GOOD X Brates Bottom plug(in place):YES,CALC Plugged through TUBING X _, CASING	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dripozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement with 3rd. plug at 345' w/40 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing. Condition of casing(in hole):GOOD X Brates Bottom plug(in place):YES,CALC Plugged through TUBING X _, CASING	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dr. pozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement wide. Sys. plug at 345' w/40 sxs. cement wide. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing. Condition of casing(in hole):GOOD X Br. Bottom plug(in place):YES, CALC Plugged through TUBING X , CASING	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dr. pozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement wide. Sys. plug at 345' w/40 sxs. cement wide. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing. Condition of casing(in hole):GOOD X Br. Bottom plug(in place):YES, CALC Plugged through TUBING X , CASING	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] with: March , Year: 94 illing ordered 190 sxs. 60/40 Circulated hole - spot and with heavy mud between all plugs. ith 1 sx. flocele. APR 0 5 1994 ADAnhy.plug:YESX_NONODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION_LIVERING DIVISION,NODakota plug:YES_X_CONSONATION_LIVERING_NO Lugging.
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dr. pozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement wide. Sys. plug at 345' w/40 sxs. cement wide. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing. Condition of casing(in hole):GOOD X Br. Bottom plug(in place):YES, CALC Plugged through TUBING X , CASING	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dr. pozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement wide. Sys. plug at 345' w/40 sxs. cement wide. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing. Condition of casing(in hole):GOOD X Br. Bottom plug(in place):YES, CALC Plugged through TUBING X , CASING	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole (circulate) J. Schmdit All[], Part[], None[X] with: March , Year: 94 illing ordered 190 sxs. 60/40 Circulated hole - spot and with heavy mud between all plugs. ith 1 sx. flocele. APR 0 5 1994 ADAnhy.plug:YESX_NONODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION DIVISION,NODakota plug:YES_X_CONSONATION_LIVERING DIVISION,NODakota plug:YES_X_CONSONATION_LIVERING_NO Lugging.
problems - No arbuckle - Mud condition Chlorides 1500 ppm at 3900'. Proposal 1 sx. F.C. Circulate hole - spot and stem - heavy mud between all plugs. 2 sx. F.C. at 1980' - 40 sxs. at 345' - Plugging Proposal Received by: Marion Plugging operations attended by agent? Completed: Hour: 7:00P.M., Day: 27, Mon Actual plugging report: Abercrombie Dripozmix - 6% gel and one sack flocele. displaced all cement through drill pipe 1st. plug at 2730' w/25 sxs. cement. 2nd. plug at 1980' w/100 sxs. cement with 3rd. plug at 345' w/40 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 4th. plug at 40' w/10 sxs. cement. 15 sxs. in rathole (circulated) Remarks: By Allied Cementing. Condition of casing(in hole):GOOD X Brates Bottom plug(in place):YES,CALC Plugged through TUBING X _, CASING	3' - Anhy. 2683' - No circulation 50 vis 9.2 wt W.L. 8.8 - 190 sxs. 60/40 pozmix - 6% gel and displace all cement through drill 5 sxs. at 2730' - 100 sxs. with one 10 sxs. at 40' - 15 sxs in rathole