STATE OF KANSAS STATE CORPORATION COMMISSION

15-039-00196-00-00

℃WELL PLUGGING RECORD

NORTH	Location of "N						
	Location as 1	IE/CNW#SW#"	or footage from	m lines SE N	<u> E</u>		
		Graybol Oi	1 Corpora	tion		_ Well No	7
	Lease Name	2200 N. B	T. Bldg	Tulsa 3.			
				Dry Hole)			
	Date 200211	npleted		. 231y 11010)			19 63
•	- 1	Application for plugging filed July 8					19 63
	Application fo	r plugging appro	ved July	8	us balancia de como de desperante de la como		19_63
	Plugging com	menced	<u>July</u>	9	popositiva obtavitionis control del visioni del monitorio del control del cont		19 63
		pleted					19 63
	Reason for aba	andonment of we	ll or producing	g formation	Dry Hole	TAIL THE STATE OF	
	76		. 1 3 C 1		and the section of th		19
	1			st production ation Division or			
Locate well correctly on above Section Plat	menced?	TP	i me conserv	ation Division or	ns agents ber	ore brugging	was com-
ame of Conservation Agent who su			L. Nich	ols, Morlan	d, Kansas		
							77_Feet
now depth and thickness of all wat							
OIL, CAS OR WATER RECO	RDS					CASING RE	CORD
						1	
FORMATION	CONTENT	FROM	70	SIZE	PUT IN	PULLED	
Severy Sand	Water	3596	3608	8 5/811	3561	None	
Topeka Lime Lansing Lime	Tight Tight	3618 3774	3659 4012				
Conglomerate	Water	4208	4232		AN ARROWAN AND ARROWS AND ARROWS THE THE PROPERTY AND THE		
Arbuckle	Water	4232	4362				
Reagan	Water	4362	4377				
						1	
Filled hole with of Portland Cemen with 20 sacks of Portland Cement f	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sac Filled h	k of hull ole with	s. Cemer 10 sacks	of
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sac Filled h	k of hull ole with	s. Cemer 10 sacks	of
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sac Filled h	k of hull ole with	s. Cemer 10 sacks A.M., Jul	of y 9,
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ole with at 8:00	s. Cemer 10 sacks	of y 9,
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ole with at 8:00	s. Cemer 10 sacks A.M., Jul	of y 9,
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ole with at 8:00	s. Cemer 10 sacks A.M., Jul	of y 9,
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMMI 12 1963	of of y 9, 1
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMM! 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMM! 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMMI 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMM! 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMM! 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of	t. Set plug a Portland cemen	t 350'. Pla t. Set plu	nced in or ng at 40°	ne-half sach Filled hog completed	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMM! 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of Portland Cement f	t. Set plug a Portland cemen rom 40' to gro	t 350'. Plate Set plumd level.	essary, use BACK	ne-half sacl Filled has completed	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMM! 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of Portland Cement f	t. Set plug a Portland cemen rom 40' to gro (If addition Graybol Oil	t 350'. Plate Set plumd level. al description is neconformation.	essary, use BACK	ne-half sacl Filled he g completed Signature Signatur	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMM! 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of Portland Cement f	t. Set plug a Portland cemen rom 40' to gro (If addition Graybol Oil	t 350'. Plate Set plumd level. al description is neconformation.	essary, use BACK	ne-half sacl Filled he g completed Signature Signatur	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMM! 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of Portland Cement f	t. Set plug a Portland cemen rom 40' to gro Graybol Oil Bank of Tulsa B	t 350'. Plate Set plumd level. aldescription is necessary comporation wilding, To	essary, use BACK	ne-half sacl Filled he g completed Signature Signatur	k of hull ple with at 8:00 REC	S. Cemer 10 sacks A.M., Jul TION COMM! 12 1963	of y 9, SSION
of Portland Cemen with 20 sacks of Portland Cement f Hame of Plugging Contractor ddress 2200 National E	t. Set plug a Portland cemen rom 40' to gro Graybol Oil Bank of Tulsa B	t 350'. Plat. Set plund level. al description is nec Corporation wilding, To	essary, use BACK	ne-half sacl Filled heg completed S Gof this sheet)	c of hull ole with at 8:00 HATE CORPOR! ULL CONSERV Wich ss.	S. Cemer 10 sacks A.M., Jul 11 VEI 11 11 11 11 11 11 11 11 11 11 11 11 11	of o
of Portland Cemen with 20 sacks of Portland Cement f ame of Plugging Contractor ddress 2200 National E TATE OF Oklahoma Lyman C. De	t. Set plug a Portland cemen rom 40' to gro Graybol dition Graybol Oil Bank of Tulsa B mis	t 350'. Plat. Set plund level. al description is nec Corporation wilding, To	essary, use BACKon Tulsa (employee of	ne-half sach Filled he g completed S of this sheet) klahoma	CONSERV	S. Cemer 10 sacks A.M., Jul 11 VEI TION 60MM! 12 1963 ATION DIVI	of of y 9, 1
of Portland Cemen with 20 sacks of Portland Cement f ame of Plugging Contractor ddress 2200 National E TATE OF Oklahoma Lyman C. De rell, being first duly sworn on oatl	cement of the growth of the graybol of th	t 350'. Plate Set plumd level. Land level. Land level. Land level. Land description is necessary to the comporation of the converse of the	essary, use BACKon Tulsa (employee of facts, statemer	re-half sack Filled has completed Sompleted Sof this sheet) klahoma. owner) or (asserted)	CONSERV	S. Cemer 10 sacks A.M., Jul 11 VEI TION 60MM! 12 1963 ATION DIVI	of y 9, SSION
of Portland Cemen with 20 sacks of Portland Cement f ame of Plugging Contractor ddress 2200 National E TATE OF Oklahoma Lyman C. De rell, being first duly sworn on oatl	cement of the growth of the graybol of th	t 350'. Plate Set plumd level. Land level. Land level. Land level. Land description is necessary to the comporation of the converse of the	essary, use BACKon Tulsa (employee of facts, statemer	re-half sack Filled has completed Sompleted Sof this sheet) klahoma. owner) or (asserted)	CONSERV	S. Cemer 10 sacks A.M., Jul 11 VEI TION 60MM! 12 1963 ATION DIVI	of y 9, SSION
of Portland Cemen with 20 sacks of Portland Cement f Portland Cement f ame of Plugging Contractor address 2200 National F TATE OF	cement of the growth of the graybol of th	t 350'. Plate Set plumd level. Land level. Land level. Land level. Land description is necessary to the comporation of the converse of the	essary, use BACKon Tulsa (employee of facts, statemer	re-half sack Filled has completed Sompleted Sof this sheet) klahoma. owner) or (asserted)	CONSERV	S. Cemer 10 sacks A.M., Jul 11 VEI TION 60MM! 12 1963 ATION DIVI	of y 9, SSION
of Portland Cemen with 20 sacks of Portland Cement f Hame of Plugging Contractor ddress 2200 National E	cement of the growth of the graybol of th	t 350'. Plate Set plumd level. Lad description is necessary to the component of the convergence of the conv	essary, use BACKon Tulsa (employee of facts, statemer	Something sach Filled has completed sompleted	sof hull ole with at 8:00 THE CORPORI JUL CONSERV Wich ss. KENERGENERA herein contain	S. Cemer 10 sacks A.M., Jul 11 VEI TION 60MM! 12 1963 ATION DIVI	of of y 9, 1
of Portland Cemen with 20 sacks of Portland Cement f ame of Plugging Contractor ddress 2200 National E TATE OF Oklahoma Lyman C. De rell, being first duly sworn on oath bove-described well as filed and the	craybol of Tulsa Bank of Tulsa	t 350'. Plate t. Set plumd level. In all description is necessary to the corporation of the composition of the condition of	essary, use BACKon Tulsa (employee of facts, statement)	Something sach Filled has completed sompleted	CONSERV	S. Cemer 10 sacks A.M., Jul 11 VEI TION 60MM! 12 1963 ATION DIVI	of of y 9, 1
of Portland Cemen with 20 sacks of Portland Cement f ame of Plugging Contractor ddress 2200 National E TATE OF Oklahoma Lyman C. De rell, being first duly sworn on oatl	craybol of Tulsa Bank of Tulsa	t 350'. Plate Set plumd level. Lad description is necessary to the component of the convergence of the conv	essary, use BACKon Tulsa (employee of facts, statement)	Something sach Filled has completed sompleted	sof hull ole with at 8:00 THE CORPORI JUL CONSERV Wich ss. KENERGENERA herein contain	S. Cemer 10 sacks A.M., Jul 11 VEI TION 60MM! 12 1963 ATION DIVI	of of y 9, 1
of Portland Cemen with 20 sacks of Portland Cement f Iame of Plugging Contractor ddress 2200 National E TATE OF Oklahoma Lyman C. De rell, being first duly sworn on oath bove-described well as filed and the	craybol of Tulsa Bank of Tulsa	t 350'. Plate t. Set plumd level. In all description is necessary to the corporation of the composition of the condition of	essary, use BACKon Tulsa (employee of facts, statement)	Something sach Filled has completed sompleted	sof hull ole with at 8:00 THE CORPORI JUL CONSERV Wich ss. KENERGENERA herein contain	S. Cemer 10 sacks A.M., Jul 11 VEI TION 60MM! 12 1963 ATION DIVI	of of y 9, 1
of Portland Cemen with 20 sacks of Portland Cement for Portland Cement for Portland Cement for Ceme	craybol of Tulsa Bank of Tulsa	t 350'. Plate t. Set plumd level. In all description is necessary to the corporation of the composition of the condition of	essary, use BACKon Tulsa (employee of facts, statement)	Something sach Filled has completed sompleted	sof hull ole with at 8:00 THE CORPORI JUL CONSERV Wich ss. KENERGENERA herein contain	S. Cemer 10 sacks A.M., Jul 11 VEI TION 60MM! 12 1963 ATION DIVI	of of ssion