Form CP-3 Rev. 6-4-68

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT RECEIVED
STATE CORPORATION COMMISSION

CER 9.34074

J. Lewis Brock
Administrator
P. O. Box 17027
Wichita, Kansas 67217

SEP 2 3 1974

CONSERVATION DIVISION Wichita, Kansas

				100	
Operator's Full Name		and and in the analysis to the state of the		angung san ang ang ang ang ang ang ang ang ang a	with the same of
Complete Address	3521 North Centi	ral Avenue, Phoe	nix, Arizona.	85012	and the second second second second
		Well No.			
Location	CSW-NE	Sec. 34	Twp. 3 Rge.	(E)	(w) <u>2</u> 8
County	Decatur		Total Depth_	4493'	
Abandoned Oil Well			1		
Other well as hereafte	r indicated				
Plugging Contractor					
Address				,	
Operation Completed:			•		
The above well was plug	gged as follows:				7 10 10 10 10 10 10 10 10 10 10 10 10 10
225'8 5/8" Surface of Top of Dakota section	casing, cement cir	culated with	The application of the all the contract of the	quaezasirskytytitti jadittijan yhtitikkojanana samuusistatti	ahinassaysicariyezaysana
Circulated hole with h	neavy mud. Pulled	l DP to 1425' and	d displaced 11	O Cu. Ft. o	ement
thru DP from 1425' to					
DP from 245' to 170'.					
cement to bottom of ce					
	Annual and a state of the state	NT OCCUPATION CONTRACTOR AND MAINTENESS OF AN ACCUPATION OF THE CONTRACTOR AND ACCUPATION OF A PRINCIPLE CONTRACTOR AND	ikan mendenti ikan kecemban perintengan pengengan pengengan pengengan pengengan pengengan pengengan pengengan Pengengan	notinny to children for a significant in stages on processing the second contraction in the seco) .
The state of the s	and an artificial state of the second of the second state of the s	0004591, 136-10 2013 98888899164, \$2 5 6 0 14 2 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	empira uzitheadam sightell survestutesek essenanciak risepes kernestiannapan krekituseksessättää	an izerbanjima ca managadine ibus napagadipan omnama seni angesi ca	nių tyriosinininining pases
I hereby certify that t	he above well was	Signed:	M.L.		enicologica en recisiono
OICED		•	Well Plugging	Supervisor	