KANSAS

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

15-039-00550-00-00

J. P. Roberts Administrator 500 Insurance Building Wichita 2, Kansas

Rev. 6-26-62
OCT 3 1950
10-3-66 Wiching, Kansas
·

Form CP-3

						*		
Operator's Full Name	Bulldog Pi	pe and Su	pply Con	mpany	Динен силоппан нам че	anamatayin 200 dilarah eriban matri 1995	chetroniessuscial Alases spectuses s	ra oprocedens en formación y o rest en en estra en
Complete Address:	Box #1153,	Tulsa, O	klahoma	Control with Adominate memory	SANT UTSETERING AND AND STREET	ungen perungan perung	Royanning reserve with the last of the l	nderstand Principal and American American State (1994)
Lease Name	Boettger	en er	n de la demandration de la constant de la constant activité de la constant activité de la constant activité de	Vell No) to	2	NORMAN, I PROPERTY AND INVESTMENT OF THE PROPERTY OF THE PROPE	MALENTEN ASSESSED AS ASSESSEDANCES AS ASSESSED AS ASSESSED AS ASSESSED AS ASSESSED AS ASSESSED AS ASSESSEDANCES AS ASSESSEDANCES.
Location	SE-SE-SE	SAESSENOVAKUSANINUSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSESSUSSE	Sec. 5	Twp	3	Pge	(B)	(W) 29
County	Decatur	BECOMOCOMPACHMENT OF THE SECOND SECTION OF THE COMMISSION CONTRACTOR	Total	l Depth	and the second	394	O	大学者がおおおけるないできまったなななないがあればっていますが
Abandoned Oil Well								
Other well as hereaf	ter indicated:	ar banka sanda makkamusundon (olimin kemamuniyak agsidin amusunda sasishirin m	names (was the construction of the large transfer of the large tra	irasidon negatori izano zezzikiateta ila dikediken l	zz wa wionen kanten kanten ka		nggerlands er om en lægt ag kantistansfoldet e konströt f	TG क्षेत्र र अञ्चलकार स्थापन स्था
Plugging Contractor:	pert Self	Casing Pu	lling C	ompan	y.	anggerin engganar yapkar engganara ka savça sakarı	essiden eti varreți varre volul legis COVANA îngle ya Paril sale	er hilliger mar zel-ego-y-go king he king king king king king king king king
Address:	R.R. #4. H	utchinson	. Kansa	S.	poddywartalnich fermore o se	Licen	so No.	48
Operation Completed:	Hourll:15A	May2	.7 Moi	2 t.D.	9	Ne.	8F 196	6 marporania managamenta antina di managamenta antina di managamenta di managamenta di managamenta di managamenta
The Above well was p	lugged as follo	ows:	,					
165'8 5/8" Surf 3930'52" Produc	ace pipe, ce	ment circ	Bot to	m hol	.e c	omplet	ion.	Садаў і і на праводня праводн
Sanded well back	to 3910' and	l set 5 sa	icks cen	ent w	ri th	dump	bailer	errations sometiment and members of the control of
Pulled 51 casing	; and squeeze	d hole wi	.th 30 s	acks	g el	follo	wed by	r 75
sacks cement. Pu	mp-in pressu	re 250#.	Binal	shut-	·in	pressi	re 100	# •
MILE TO THE PROPERTY OF THE PR	(Recove	ered 1700	5½" ca	sing)	on and the second se	z Winderschaft Mehrbeiter und seiner Stellen	elsendenessen anderson anderson anderson anderson anderson anderson and anderson and and and and and and and a	resultanicos spinosala sepresanada conformación (foto)
(Mudding and	cementing or	<u>erations</u>	perform	ied by	т На	llibu	ton Co	ancia un remanda a monte de la compositio de la compositi
I hereby certify tha	t the above we	ll was plug			state	id. 1		en e
Contraction of the Contraction o	VOICE	D	Si	lgned:	Wel	i Plug	ging Su	pervisor
DATE		rise.	•			•		
INV. N	4 4	7-w						