4-<u>031846</u>

TO: '	API number: $15-023-20,078-00-00$
STATE CORPORATION COMMISSION	
CONSERVATION DIVISION - PLUGGING	<u>C SE SE</u> /4 SEC. <u>06 , 03 S, 41</u> W
200 COLORADO DERBY BUILDING	feet from S section line
WICHITA, KANSAS 67202	_660 feet from E section line
Operator license#_5099_	Lease_Hilt well #_1
	1011 <u>1</u>
Operator: J-W Operating Company	County Chevenne
Address: P.O. Box 305 Wray, Colorado 80758	- 2 30
Address: D O Roy 205	Woll total donth 1640 foot 52.
Wrote Coloredo 00750	well total depth 1640 feet
	Conductor Pipe: 0 inch 0 0 feet
	Surface pipe 8 5/8 Inch @ 335 feet
31 2 12 33	
Aband. oil well, Gas well _X_, Inp	out well, SWD, D & A
Plugging contractor: Excell Drilling	License# 2989
Address: Wray, Colorado	
Company to plug at: Hour: A.M. Day:	9-10 Month Nuguet Voor 02
bay.	Fig. Month. Rugust 1ear: 93
Plugging proposal received from: Roland Leton-BLM and Ray Bivens J-W	
riagging proposal received from: koland Leton-BLM and Ray Bivens J-W	
	_
Company: J-W Operating - Bureau of Lan	<u>id</u> Phone:
Management	
Were: Order 140 sxs. common cement. Cementers Inc Scottbluff,	
	Nebraska.
Diverging Dyonogol Descioud has gont of	1 9
Plugging Proposal Received by: <u>Carl G</u>	oodrow
Plugging operations attended by agent?	All[], Part[X], None[]
Completed: Hour: P.M. Day: 9-10, Mo	onth: August , Year: 93
Actual plugging report: 8 5/8" set @	335' W/310 sx. cwc. 4 1/2" set @
1634' W/125 sxs. P.B.T.D. 1634'. Perf	's. 1510! - 1534! Loaded hole with
KCL water. Set wireline CIBP @ 1460'.	Shot off casing 6 0521 Dulled
4 1/2" washed down 953' to 1167'. Ran	2 2/9H tubing to 11671 Wale fill
un circulated 40 eye coment to come	Dulled C.
up, circulated 40 sxs. cement to 885'.	Pulled 2 3/8" up to 450'
circulated 80 sxs. cement to 170'. Pu	lled 2 3/8" to 390' circulated
cement to surface with 20 sxs. Used t	otal of 140 sxs. common cement.
Cut off and weld plate on 8 5/8". Bac	k fill cellar. Plug complete.
	ALD rent
Remarks:	
Condition of casing (in hole); GOOD_X	AD Ahby plug: YES X NO
Bottom plug(in place):YES X, CALC	NO Dakota plug:YES X, NO
Plugged through TUBING, CASING X	
	.@ Y Wo Yaki QVarion! CI.
	#Ievation: GL
STA	The Control of the Co
I diff[] observe the p	lugging. Cal Goodwa
I diff[] observe the p	lugging. Cal Hoodwar
I diff[] observe the p	lugging. Cal Hoorling (agent)
I diff[] observe the p	lugging. Cal Hoodwar
STA	lugging. Cal Hoorling (agent)