TO: /0-//	API Number: 15-065-21483-00-01
STATE CORPORATION COMMISSION	
CONSERVATION DIVISION - PLUGGING	<u>S2 S2 SE</u> /4 SEC. <u>15, 07 S, 22 W</u>
130 SOUTH MARKET, SUITE 2078	feet from S section line
WICHITA, KANSAS 67202	1320 feet from E section line
Operator license#_5386_	Lease: Nichol Well # 2
Operator: Production Drilling, Inc.	County: Graham
Address: 1023 Reservation Road	Well total depth 3862 125.5 feet
Hays, Kansas 67601	Conductor Pipe: 0 inch @ 0 feet
Larry Patterson	Surface pipe 8 5/8 Inch @ 243 feet
Aband. oil well, Gas well, Input well_	, SWD_ x , D & A
Plugging contractor: Allied Cementing Comp	any License# 13
Frugging contractor: Arried Cementing Comp	any Dicenses
Address: Russell, Kansas 67665	
Company to plug at: Hour: A.M. Day: 11	Month: October Year: 1996
	project. Month of
Plugging proposal received from: Marty Patte	rson
Company: Production Drilling, Inc.	Phone: 913-625-1189
Were: 8 5/8" - 243' S.P. w/180 sxs cmt. 4 1/2	W gaging gab at 20621 w/175 gag gament
Anhy. 1933' - Plug back T.D. 1758' - Casing was	
	458' with 180 sxs. Pump in with pump truck. shut in under pressure - squeeze 4 1/2" x 8
Load 4 1/2" casing with cement top to bottom -	shut in under pressure - squeeze 4 1/2" x 8
	shut in under pressure - squeeze 4 1/2" x 8
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press	shut in under pressure - squeeze 4 1/2" x 8
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel -
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls.	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel -
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel -
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt nth: October , Year: 1996
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt], Part[], None[] nth: October
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck.	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt nth: October , Year: 1996
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface.	<pre>shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt [], Part[], None[] nth: October</pre>
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement	<pre>shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt [], Part[], None[] nth: October</pre>
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface.	<pre>shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt [], Part[], None[] nth: October</pre>
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement	<pre>shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt [], Part[], None[] nth: October</pre>
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement	<pre>shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt [], Part[], None[] nth: October</pre>
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement	<pre>shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt [], Part[], None[] nth: October</pre>
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt], Part[
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement added. Max. P.S.I. 500#. S.I.P. 200#.	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt], Part[
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M., Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement added. Max. P.S.I. 500#. S.I.P. 200#. Remarks: Cemented by Allied Cement Company.	<pre>shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt [], Part[], None[] nth: October</pre>
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement added. Max. P.S.I. 500#. S.I.P. 200#. Remarks: Cemented by Allied Cement Company. Condition of casing(in hole): GOOD_ BAD_	<pre>shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt [], Part[], None[] nth: October</pre>
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement added. Max. P.S.I. 500#. S.I.P. 200#. Remarks: Cemented by Allied Cement Company. Condition of casing(in hole): GOOD BAD Bottom plug(in place): YES , CALC , NO Plugged through TUBING , CASING .	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt], Part[
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement added. Max. P.S.I. 500#. S.I.P. 200#. Remarks: Cemented by Allied Cement Company. Condition of casing(in hole): GOOD BAD Bottom plug(in place): YES_, CALC_, NO_	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt], Part[
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by:Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report:Production Drilling of hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement added. Max. P.S.I. 500#. S.I.P. 200#. Remarks:Cemented by Allied Cement Company. Condition of casing(in hole): GOOD BAD Bottom plug(in place): YES, CALC, NO Plugged through TUBING, CASING I did(XX) / Git not[] observe the plugging	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt [], Part[], None[] nth: October, Year: 1996 rdered 250 sxs 60/40 pozmix - 10% gel - 5 sxs followed with 100 sxs cement and 5 sxs hulls Anhy.plug: YES_X, NO Dakota plug: YES_X, NO Elevation:GL
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour:11:30 A.M., Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement added. Max. P.S.I. 500#. S.I.P. 200#. Remarks: Cemented by Allied Cement Company. Condition of casing(in hole): GOOD_ BAD_ Bottom plug(in place): YES, CALC, NO_ Plugged through TUBING, CASING I did(X) / Gif npt[] observe the plugging	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt], Part[
Load 4 1/2" casing with cement top to bottom - 5/8" annulus with cement. Shut in under press 5 sxs hulls. Plugging Proposal Received by: Marion J. Sch Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M. , Day: 11 , Mo Actual plugging report: Production Drilling o hulls. Pumped in with pump truck. 1) Annulus cement visable at surface. 2) Pumped in 4 1/2" casing with 100 sxs cement added. Max. P.S.I. 500#. S.I.P. 200#. Remarks: Cemented by Allied Cement Company. Condition of casing(in hole): GOOD BAD Bottom plug(in place): YES , CALC , NO Plugged through TUBING , CASING .	shut in under pressure - squeeze 4 1/2" x 8 ure. Order 250 sxs 60/40 pozmix - 10% gel - midt], Part[