


## CARD MUST BE TYPED

## State of Kansas NOTICE OF INTENTION TO DRILL

CARD	MUST	ΒE	SIGNED
	_		

56A -465

EFFECTIVE DATE		-19.03	_	Н	UGOT	ON INFILL						•
Starting Date		07/06/05				API Numb	er <u>15-175-2</u>	1973 - 🗅	0-0	0		
	month	day	year	_								
							IS SECTION					IRREGULAR
<b>OPERATOR</b> : Licen	nse#			V	<b>*</b>	NW NW	SE	NW S	Sec11	Twp	33 S Rr	ng <u>33 W</u>
Name		OXY USA I	nc.				3780			Ft.	from South	line of Section
Address		P.O. Box 25					3880					Line of Section
City/State/Zip		Liberal, KS					ch acreage attr					wells
Contact Person							of acres attrib				640	
Phone		(620) 629-4	242	-/-			icing well from					_
action (and				V		Same con	nmon source of	f supply		1'	750	feet
CONTRACTOR: I							or unit bounda				.400	feet
Name		Murfin Drilling				County			Seward			
City/State/Zip	\.	Wichita, KS 6	7202	OH HILL		Lease Name	1	Hunt	F	784	Well #	
Well Drilled as:	New	X Recom	pletion	OWW0	-		ce elevation _					feet MSL
Projected Total Depti	n	289	73		feet	-	om of fresh wa					
Formation		Hugoton Cha	se			•	om of usable w	ater				
If OWWO or Recom	pletion: (	old well info as	follows:			Surface pipe	•			1 <u>X</u>	_ 2	
Operator		OXY USA.	Inc.				planned to be s			1683		
Well Name		Hunt F-					for Drilled Op					
Comp Date	Pendin	g (	Old Total Dep	th <u>63</u>	30	DWR Permit	#:		<u>X</u> w	ell	_ farm pond	other
I certify that well wil Date August 1, 2005	l comply	with K.S.A. 55	-101, et seq. ignature of (	, plus event Operator or A	ually plug Agent	ging hole to K	CC Specifica	ations.	Title Ca	apital Proj	ect	
For KCC Use: Conductor Pipe Requ This Authorization E	uired	NONE 8-14-05		fe	eet; Mini	mum Surface l Approved E	Pipe Required By <u>化ゴピュ</u>	1 48 14-05	0 N=P	8.3.0	feet p	er Alt. 1=2 8 · 18 · 0 ≤ 9/95
TS: NWN	N5EN	ω <b>υ</b> ω		* (	~ AS:	St. Louis Hugoton I	test. nfillwel	J				9193
		This can		led with K.C	C.C. five	(5) days prior t in six (6) mont	o commencin	g well	ζ.C.C			
	A Re	egular Section o	of Land			Important p	rocedures to	follow:				



- 1. Notify District office before setting surface casing.
- 2. Set surface casing by circulating cement to the top.
- 3. File completion forms ACO-1 with K.C.C. within 120 days of well spud date, following instructions on ACO-1, side 1, and including copies of wireline logs.
- 5. Notify District office 48 hours prior to old well workover or re-
- 6. If an alternate 2 completion, cement in the production pipe from below any useable water to surface within 120 days of spud

State Corporation Commission of Kansas Conservation Division 130 S. Market Room 2078 Wichita, Kansas 67202-1212 (316) 337-6231

RECEIVED AUG 0 3 200E KCC WICHITA